

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 30 S., R. 7 W.

CHAINS

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 30 S R 7 W
 $\frac{1}{4}$ $\frac{S 10}{S 15}$
 1965

from which

A fir, 9 ins. diam., bears N. $10\frac{1}{2}^{\circ}$ E., 32 lks. dist., marked $\frac{1}{4}$ S10 BT.

A fir, 11 ins. diam., bears S. 57° E., 52 lks. dist., marked $\frac{1}{4}$ S15 BT.

Ascend 650 ft. over E. slope, changing to NE. slope.

61.20 Ridge, bears NW. and SE.; also jeep trail, 10 lks. wide, bears same; desc. 255 ft. over SW. slope.

72.10 Ravine, drains S.; asc. 235 ft. over SE. slope.

79.00 Spur, slopes S.; desc. 40 ft. over SW. slope.

82.12 The cor. of secs. 9, 10, 15 and 16.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, white fir, cedar, madrone, pine, yew, chinquapin, live oak, oak, and hemlock; undergrowth, vine maple, hazel, poison oak, Oregon grape, salal, manzanita, huckleberry, blackberry, fern, and ocean spray.

From the cor. of secs. 21, 22, 27 and 28.

S. $89^{\circ} 36'$ W., bet. secs. 21 and 28.

Ascend 90 ft. over NE. slope, through heavy timber and dense undergrowth.

10.50 Spur, slopes N.; desc. 75 ft. over NW. slope.

18.50 Creek, 3 lks. wide, course N. 50° E.; asc. 5 ft. over SE. slope.

19.79 True point for the E 1/16 sec. cor. of secs. 21 and 28, falls in a creek, 3 lks. wide, from S. 60° W., course S. 40° E., where it is impracticable to establish a permanent monument.

Ascend 4 ft. over SE. slope.

19.99 Point for the witness corner to the E 1/16 sec. cor. of secs. 21 and 28.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

E 1/16 $\frac{S 21}{S 28}$ WC \rightarrow
 1965

Fd. ok. Brass cap out of place and buried
 we reset. BTs ok. DCSO 11/1969 CS 53/40-98

from which

A white fir, 20 ins. diam., bears N. 79° E., 47 lks. dist., marked X BT.