

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 30 S., R. 7 W.

## CHAINS

A white fir, 12 ins. diam., bears S. 20° E., 31 lks. dist., marked X BT.

Ascend 360 ft. over SE. slope.

39.58

The  $\frac{1}{4}$  sec. cor. of secs. 21 and 28, perpetuated by the Douglas County Surveyor in 1965, monumented with an iron post, 1 in. diam., firmly set, extending 6 ins. above the ground, with brass cap mkd.

## COUNTY SURVEYOR OFFICE

T 30 S

 $\frac{1}{4}$  S 21

S 28

R 7 W

1965

from which the original bearing trees

A down and rotted madrone, 9 ins. diam., bears N. 25° E., 14 lks. dist., with fragmentary scribe marks visible on rotted double blaze.

A down and rotted madrone, 7 ins. diam., bears S. 20° W., 5 lks. dist., no marks remaining.

and County Surveyor's bearing trees

A fir, 25 ins. diam., bears N. 55° E., 10 lks. dist., marked  $\frac{1}{4}$  S21 CS BT on double blaze.

A fir, 23 ins. diam., bears S. 34° W., 14 lks. dist., marked  $\frac{1}{4}$  S28 CS BT on double blaze.

Add marks BLM 1965 to brass cap.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, white fir, cedar, madrone, pine, yew, chinquapin, live oak, oak, and hemlock, undergrowth, vine maple, hazel, poison oak, Oregon grape, salal, manzanita, huckleberry, blackberry, fern, and ocean spray.

## GENERAL DESCRIPTION

The lands included in the foregoing survey are situated about 8 miles westerly of the town of Riddle, Oregon. Access is gained by way of Doe Creek Road, a dirt and gravelled road which extends northerly from Glenbrook Loop Road.

The area is drained by Little Doe Creek, Cookhouse Creek, and Buck Creek, all of which flow southerly into Cow Creek, and by several small creeks flowing northerly into Thompson Creek. Elevations range from about 1,500 feet above sea level at Buck Ck. near the corner of secs. 21, 22, 27 and 28, to about 2,365 feet above sea level at the corner of sections 9, 10, 15 and 16.

Soil is generally composed of rocky, clay loam. Much of the privately owned lands in the area have been logged or are now being logged, the remainder is covered with old growth timber which consists primarily of fir, with stands of cedar, pine, yew, madrone, chinquapin, live oak, oak, maple, and hemlock, with undergrowth of vine maple, hazel, poison oak, Oregon grape, salal, manzanita, huckleberry, blackberry, fern, and ocean spray.

There were several mining claims noted in the area.

The average of a considerable number of readings throughout the entire area gives a mean magnetic declination of 19° 50' E., with a range of 1° 45' in local attraction.