

County Surveyor's Record, Douglas County, Oregon

Remonumentation of Certain Original Corner Points
T. 23 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

A down hemlock, 10 ins. diam., bears S. 37° E.,
30 lks. dist., with partial scribe marks
visible on opened blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins.
in the ground, with brass cap mkd.

$$\begin{array}{r} T\ 23\ S\ R\ 8\ W \\ \frac{1}{4} \quad \frac{S\ 32}{T\ 24\ S} \\ 1963 \end{array}$$

from which

A hemlock, 40 ins. diam.; bears N. 36° E., 78 lks.
dist., mkd. ¼ S32 BT.

A hemlock, 6 ins. diam., bears N. 53½° W., 123 lks.
dist., mkd. ¼ S32 BT.

Reset the aluminum pipe alongside the iron post.

The cor. of secs. 31 and 32 only, S. bdy. of the Twp.,
determined at record distance from the remaining original
bearing trees:

A burned hemlock stump, size indeterminate, bears
N. 55° E., 45 lks. dist., with no marks remaining.

A hemlock, snag, 30 ins. diam., bears S. 16½° E.,
55 lks. dist., with partial scribe marks visible
on opened and burned blaze.
(Record bearing, S. 18° E.)

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins.
in the ground, with brass cap mkd.

$$\begin{array}{r} T\ 23\ S\ R\ 8\ W \\ \frac{S\ 31\ | \ S\ 32}{S\ 5} \\ T\ 24\ S \\ 1963 \end{array}$$

from which

A hemlock, 5 ins. diam., bears N. 37° E., 101 lks.
dist., mkd. T23S R8W S32 BT.

A hemlock, 9 ins. diam., bears N. 34½° W., 56 lks.
dist., mkd. T23S R8W S31 BT.