

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of S. Bdy., T. 29 S., R. 8 W.

CHAINS

S. 89° 23' W., on the S. bdy. of sec. 31, marking and blazing the true line.

Ascend 155 ft. over NE. slope, along S. edge of logged area, through light undergrowth.

6.55 Spur, slopes N. 10° W.; desc. 140 ft. over broken NW. slope.

40.03 The  $\frac{1}{4}$  sec. cor. of sec. 31 only, perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1958, monumented with an iron post, 1 $\frac{1}{2}$  ins. diam., firmly set, extending 12 ins. above ground, with brass cap mkd.

## COUNTY SURVEYORS OFFICE

	T 29 S	R
$\frac{1}{4}$	S 31	8
	S 6	W

T 30 S

from which the remains of the ~~1958~~<sup>1958</sup> original bearing trees:

A sawed fir stump, 24 ins. diam., bears North, 16 lks. dist., mkd. BT on opened blaze.

A stump hole, bears S. 20° W., 29 lks. dist.

and bearing trees marked by Byron

A fir, 16 ins. diam., bears N. 36° E., 59 $\frac{1}{2}$  lks. dist., mkd. with a partially healed double blaze.

A fir, 21 ins. diam., bears S. 24 $\frac{1}{2}$ ° E., 72 $\frac{1}{2}$  lks. dist., mkd. with a partially healed double blaze.

At the corner point

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$  ins. diam., 22 ins. in the ground, with brass cap mkd.

	T 29 S R 8 W
$\frac{1}{4}$	S 31
	1965

from which a new bearing tree

A fir, 18 ins. diam., bears N. 66° W., 61 lks. dist., mkd.  $\frac{1}{4}$  S31 BT.

Reset the county iron post inverted alongside the the iron post.

S. 88° 57' W., beginning new measurement

Descend 130 ft. over SW. slope, through logged area and dense undergrowth.

6.60 Creek, 3 lks. wide, course N. 30° W.; asc. 110 ft. over broken NE. slope.

14.65 Spur, slopes N. 10° W.; desc. 105 ft. over broken NW. slope.

24.75 Creek, 2 lks. wide, course N. 10° W.; asc. 90 ft. over NE. slope.