

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion Subdivisional Lines, T. 23 S., R. 7 W., W. M.

CHAINS

County Surveyors Office in 1958, with an iron post, 1 in. diam., firmly set, projecting 12 ins. above ground, with brass cap marked

COUNTY SURVEYORS OFFICE
T 23 S R 7 W
1/4 S 17 S 16
1958

FO. OK JAN. 1994
BY BENTZ M 119-2A

from which an original bearing tree

A white oak, 30 ins. diam., bears N. 51° E., 132 lks. dist., with scribe marks 4 S visible on opened blaze.

and trees marked by J. W. Byron, Deputy County Surveyor in 1958

A fir, 30 ins. diam., bears S. 35½° E., 34 lks. dist., with fragmentary scribe marks visible on pitched over double blaze.

A fir, 48 ins. diam., bears S. 30° W., 44 lks. dist., with fragmentary scribe marks visible on pitched over double blaze.

North, beginning new measurement.

Ascend 20 ft. over S. slope.

2.00 Ridge, bears N. 65° W. and S. 65° E.; desc. 155 ft. over NE. slope.

7.90 Ravine, drains N. 80° E.; asc. 35 ft. over SE. slope.

9.80 Spur, slopes N. 50° E.; desc. 195 ft. over NE. slope.

11.75 Enter logged area, edge bears E. and W.

18.05 Creek, 1 lk. wide, course N. 70° E.; asc. 35 ft. over SE. slope.

21.25 Spur, slopes N. 85° E.; desc. 125 ft. over broken NE. slope.

25.00 Leave logged area, edge bears E. and W.

40.96 The corner of secs. 8, 9, 16, and 17, monumented with the base of an oak post, 10 x 8 ins. in cross section, 18 ins. long, firmly set, 18 ins. in the ground. There is no remaining evidence of the original corner. The corner point is substantiated by a signed statement from Mr. Keith Kestersen, a long time property owner and resident of the area, attesting to the true corner position. The Statement is hereinafter attached.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap marked

T 23 S R 7 W
S 8 | S 9
S 17 | S 16
1965

FO. OK JAN 1994
BY BENTZ M 119-2A

from which