

County Surveyor's Record, Douglas County, Oregon

Dependent resurvey, Portion Subdivisional Lines, T. 23 S., R. 7 W.

CHAINS	
	<p>A maple, 30 ins. diam., bears S. 66° W., 55½ lks. dist., with scribe marks T23S R7W S19 CS BT. visible on unhealed double blaze.</p> <p>A white fir snag, 17 ins. diam., bears N. 52° W., 24½ lks. dist., with scribe marks T23S R7W S18 CS BT visible on unhealed double blaze.</p> <p>and new bearing trees</p> <p>A white fir, 18 ins. diam., bears N. 8° E., 159 lks. dist., mkd. T23S R7W S17 BT.</p> <p>A fir, 4 ins. diam., bears S. 28¼° E., 26 lks. dist., mkd. T23S R7W S20 BT.</p> <p>A white fir, 24 ins. diam., bears N. 7° W., 118 lks., dist., mkd. T23S R7W S18 BT.</p> <p>The cor. falls on ridge, bears N. 10° E. and S. 10° W.</p> <p>Land, mountainous. Soil, sandy clay loam. Timber, fir, hemlock, cedar, maple, alder, myrtle, chinquapin, and madrone; undergrowth, vine maple, salmonberry, huckle= berry, hazel, arrowwood, Scotchbroom, poison oak, salal, Oregon grape, blackberry, ceanothus, and fern.</p>
	<p>N. 0° 28' E., bet. secs. 17 and 18.</p> <p>Descend 20 ft. along W.slope, through scattering timber and dense undergrowth.</p>
3.25	Head of ravine, drains S. 70° W.; asc. 40 ft. over broken SW. slope.
9.70	Top of ascent, slopes W.; desc. 225 ft. over N. slope, changing to NW. slope.
19.405	Point for the S 1/16 sec. cor. of secs. 17 and 18.
	Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.
	<p>S 1/16 S 18 S 17 1965</p>
	from which
	<p>A white fir, 23 ins. diam., bears N. 75° E., 85 lks. dist., mkd. S1/16 S17 BT.</p> <p>A fir, 13 ins. diam., bears N. 41½° W., 109 lks. dist., mkd. S1/16 S18 BT.</p> <p>Descend 20 ft. over NW. slope.</p>
20.55	Ravine, drains W.; asc. 75 ft. over SW. slope.
24.15	Spur, slopes W.; desc. 25 ft. over NW. slope.
28.50	Bottom of descent, slopes W.; asc. 160 ft. over SW. slope.
38.81	Point for the ¼ sec. cor. of secs. 17 and 18, at proportionate distance; there is no remaining evidence of the original corner.