

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 7, T. 30 S., R. 3 W.

CHAINS	
	<p>A maple, 12 ins. diam., bears S. 78° E., 48 lks. dist., with illegible scribe marks on partly healed double blaze.</p> <p>Descend 155 ft. over NW. slope, changing to N. slope.</p>
47.20	Enter open pasture land, edge bears generally E. and W.
53.00	Days Creek, 10 lks. wide, course S. 80° W.; asc. 30 ft. over S. slope.
55.45	County road, asphalt paving, 30 lks. wide, bears N. 80° E. and S. 80° W.
57.86	Intersect the S. wall of a wood frame house at a point 35 lks. W. of the SE. corner. The house is 48 x 69 ft. in size; longside bears E. and W.
58.73	The $\frac{1}{2}$ sec. cor. of sec. 7 only/
	<p>From the $\frac{1}{2}$ sec. cor. of secs. 7 and 8.</p> <p>S. 86° 28' W., on the E. and W. center line of sec. 7.</p> <p>Descend 55 ft. over broken SW. slope, across logged area, through scattering timber and light undergrowth.</p>
6.50	Ravine, drains SW.; asc. 5 ft. over SE. slope.
8.60	Top of ascent, slopes S.; desc. 90 ft. over SW. slope.
18.35	Bailey Galch Creek, 1 lk. wide, course N. 20° W.; asc. 30 ft. over NE. slope.
19.64	Point for the center E 1/16 sec. cor. of sec. 7.
	<p>Set an iron post, 28 ins. long, 2$\frac{1}{2}$ ins. diam., 14 ins. in the ground, to bedrock, and in a mound of stone, 2 ft. base, to top, with brass cap mkd.</p> <p style="text-align: center;"> $C \frac{E \frac{1}{16}}{S \ 7} C$ 1965 </p> <p>from which</p> <p>A white fir, 8 ins. diam., bears N. 58$\frac{1}{2}$° W., 62 lks. dist., mkd. C E1/16 S7 BT.</p> <p>A fir, 15 ins. diam., bears S. 60$\frac{1}{2}$° W., 35 lks. dist., mkd. C E1/16 S7 BT.</p> <p>From this point, an iron pipe, 3/4 in. diam., firmly set extending 3 ins. above ground, bears S. 57° E., 0.23 chs. dist.</p> <p>Ascend 295 ft. over NE. slope.</p>
30.00	Spur, slopes N.; desc. 215 ft. over NW. slope.
36.015	From this point, a point established by Robert M. Thompson, Registered Engineer, in 1956, bears South,