

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisinnal Lines, T. 28 S., R. 4 W.

CHAINS

COUNTY SURVEYORS OFFICE

T 28 S R 4 W

 $\frac{1}{4}$ S 13

S 24

1957

from which the original bearing trees

A maple, 22 ins. diam., bears North, 58 lks.
dist., with rotted face. (Record, 62 lks.)

A double fir, 48 ins. diam., bears S. 3° W.,
71 lks. dist., with scribe marks $\frac{1}{4}$ S BT
visible on bark blaze. (Record, South)

and a bearing tree marked by Byron

A white fir, 24 ins. diam., bears N. 61° E., 26 lks.
dist., with fragmentary scribe marks visible on
partly healed double blaze.

Add marks BLM 1965 to brass cap.

S 89° 55' W., beginning new measurement.

Descend 235 ft. over W. slope, across old logged area,
through heavy young timber and dense undergrowth.

- 6.70 North Myrtle Creek, 20 lks. wide, course S.; asc. 40 ft.
over gradual E. slope.
- 13.20 Gravelled road, 25 lks. wide, bears N. and S.
- 14.05 Dirt road, 10 lks. wide, bears N. 50° W. and S. 15° E.
- 16.05 Creek, 2 lks. wide, course S. 30° E.; asc. 75 ft. over
N. E. slope.
- 19.69 Point for the W 1/16 sec. cor. of secs. 13 and 24.
- Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 26 ins.
in the ground, with brass cap mkd.

W 1/16 $\frac{S 13}{S 24}$
1965

from which

A hemlock, 11 ins. diam., bears N. 69 $\frac{1}{2}$ ° E., 36 lks.
dist., marked W 1/16 S13 BT.

A hemlock, 14 ins. diam., bears S. 6° W., 25 lks.
dist., marked W 1/16 S24 BT.

Ascend 265 ft. over broken N. E. slope.

- 30.70 Spur, slopes S. E.; asc. 25 ft. along S. slope.
- 34.50 Top of ascent, slopes S.; desc. 20 ft. over S. W. slope.
- 39.38 The cor. of secs. 13, 14, 23 and 24.

Land, mountainous.

Soil, ricky clay loam.

Timber fir, white fir, hemlock, cedar, madrone, yew
chinquapin, oak, maple, and dogwood; undergrowth, vine
maple, poison oak, ocean spray, fern Oregon grape,
salal, willow, manzanita and hazel.