

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 28 S., R. 4 W.

CHAINS

Land, mountainous.
Soil, rocky clay loam.
Timber, fir, white fir, cedar, hemlock, madrone, yew,
chinquapin, oak, maple, and dogwood; undergrowth, vine
maple, poison oak, ocean spray, fern, Oregon grape, salal,
willow, manzanita, and hazel.

From the cor. of secs. 13, 14, 23 and 24.

N. 89° 27' W., bet. secs. 14 and 23.

Descend 20 ft. over S.W. slope, across logged area,
through scattering timber and dense undergrowth.

- 2.37 Creek, 1 lk. wide, course S. 20° E.; asc. 120 ft.
over S.E. slope.
- 7.00 Spur, slopes S. 15° E.; desc. 75 ft. over S.W. slope.
- 10.30 Creek, 1 lk. wide, course S. 15° E.; asc. 90 ft. over
S.E. slope.
- 14.70 Spur, slopes S. 15° E.; desc. 50 ft. over S.W. slope.
- 19.50 Creek, 1 lk. wide, course S. 25° E.; asc. 130 ft. over
S. E. slope.
- 23.30 Spur, slopes S. 20" E.; desc. 95 ft. over S. W. slope.
- 27.35 Old miners ditch, 15 ft. deep, drains S.W.; desc. 135 ft.
over S.W. slope.
- 36.65 Creek, 2 lks. wide, course S.; asc. 90 ft. over E. slope.
- 39.09 Point for the $\frac{1}{4}$ sec. cor. of secs. 14 and 23, at proportionate
distance; there is no remaining evidence of the original
corner.
- Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins.
in the ground, with brass cap mkd.
- T 28 S R 4 W
 $\frac{1}{4}$ S 14
S 23
1965
- from which
- A cedar, 30 ins. diam., bears N. 40° W., 72 lks.
dist., marked $\frac{1}{4}$ S14 BT.
- A cedar, 8 ins. diam., bears S. 0 $\frac{1}{2}$ ° E., 43 lks.
dist., marked $\frac{1}{4}$ S23 BT.
- Ascend 205 ft. over E. slope, along S. edge of logged
area
- 45.00 Spur, slopes S. 20° E.; desc. 80 ft. over S.W. slope.
- 51.20 Ravine, drains S.; asc. 110 ft. over S.E. slope.
- 56.30 Spur, slopes S.; desc. 110 ft. over S.W. slope.
- 63.60 Ravine, drains S.; asc. 57 ft. over S.E. slope.
- 70.00 Spur, slopes S.; desc. 30 ft. over S.W. slope.
- 72.00 Ravine, drains S. 15° E.; asc. 70 ft. over S.E. slope