

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 28 S., R. 4 W.

CHAINS

78.18

The cor. of secs. 14, 15, 22 and 23, monumented with a wooden stake, 3 ins. square, firmly set, extending 30 ins. above the ground, from which the remains of the original bearing trees:

A rotted madrone stump, 20 ins. diam., bears N. 77° E., 47 lks. dist., no marks remaining. (Record, N. 75° E., 45 lks.)

A madrone root crown, bears S. 48° E., 31 lks. dist.

The rotted remains of a fir stump, size indeterminate, bears S. 47° W., 48 lks. dist.

The rotted remains of a fir stump, size indeterminate, bears N. 85° W., 28 lks. dist.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 28 S R 4 W
 S 15 | S 14
 S 22 | S 23
 1965

from which new bearing trees

A chinquapin, 9 ins. diam., bears N. 44½° E., 56 lks. dist., marked T28S R4W S14 BT.

A madrone, 7 ins. diam., bears S. 45½° E., 33 lks. dist., marked T28S R4W S23 BT.

A fir, 10 ins. diam., bears S. 13° W., 72 lks. dist., marked T28S R4W S22 BT.

A cedar, 7 ins. diam., bears N. 55° W., 69 lks. dist., marked T28S R4W S15 BT.

Deposit wooden stake alongside iron post.

The corner is located at a cutting corner, areas to the N.E. and S.W. have been logged.

Land, mountainous.

Soil, rocky clay loam.

Timber,

fir, white fir, cedar, hemlock, madrone, yew, chinquapin, oak, maple, and dogwood; undergrowth, vine maple, poison oak, ocean spray, fern, Oregon grape, salal, willow, manzanita, blackberry, and hazel.

From the cor. of secs. 14, 15, 22 and 23.

N. 89° 22' W., bet. secs. 15 and 22.

Ascend 10 ft. over S.E. slope, along the N. edge of logged area, through scattering timber and dense undergrowth.

1.00 Spur, slopes S.; desc. 20 ft. over S.W. slope.

3.00 Ravine, drains S. 30° W.; asc. 145 ft. over S.E. slope.

16.50 Spur, slopes S. 20° W.; desc. 685 ft. over W. slope.