

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 22 S., R. 7 W.

CHAINS

S. 89° 43' W., beginning new measurement.

Descend 60 ft. over SW. slope.

1.00 Enter open pasture land, edge bears N. and S.

17.50 Creek, 1 lk. wide, course S. 35° W.; asc. 10 ft. over SE. slope.

20.35 Point for the W 1/16 sec. cor. of secs. 15 and 22.

Set an iron post, 28 ins. long, 2½ ins. diam., 12 ins. below the surface of the ground, in a cattle feed lot, with brass cap mkd.

W 1/16 $\frac{S\ 15}{S\ 22}$
1965

from which

An iron post, 28 ins. long, 2½ ins. diam., set 22 ins. in the ground, for a reference monument, bears N. 70° E., 99 lks. dist., with brass cap mkd. W 1/16 S15 RM 1965 and an arrow pointing to the corner.

A fir, 22 isn. diam., bears S. 14° W., 295 lks. dist., mkd. W 1/16 S22 BT.

Corner is at top of ascent, slopes S.; desc. 5 ft. along broken S. slope.

37.30 Oiled road, 20 lks. wide, bears N. and S.

39.80 Wire fence, bears N. and S.

40.70 The cor. of secs. 15, 16, 21 and 22, monumented with an iron pipe, ¾ in. diam., firmly set, extending 14 ins. above the ground, This position is harmoniously related to existing original corners, has long been recognized as the cor. by adjacent land owners, and is substantiated by the remains of an original bearing tree:

An oak stump hole and decayed roots, bears S. 23° W., 245 lks. dist. (The distance to this tree was omitted in the original record.)

I accept this as the best existing evidence of the original corner postion.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 22 S R 7 W
 $\frac{S\ 16\ S\ 15}{S\ 21\ S\ 22}$
1965

*FD. OK - R. DEAN
7/81 M 88-25*

from which

An oak, 13 ins. diam., bears N. 37° W., 26½ lks. dist., mkd. T22S R7W S15 BT.

An oak, 13 ins. diam., bears S. 28° E., 42 lks. dist., mkd. T22S R7W S22 BT.

An oak, 15 ins. diam., bears S. 47° W., 73½ lks. dist., mkd. T22S R7W S21 BT.

*S. TYPE CORNER -
CORRECTED
7-30-81
J.R.*