

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 22 S., R. 7 W.

CHAINS

A cedar, 18 ins. diam., bears N. $59\frac{1}{2}^{\circ}$ E., 39 lks.
dist., with partly healed blaze.

A fir snag, 13 ins. diam., bears S. 39° W., 38 lks.
dist., with partly healed blaze.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins.
in the ground, with brass cap mkd.

$$\begin{array}{r} T\ 22\ S\ R\ 7\ W \\ \frac{1}{4} \quad \frac{S\ 10}{S\ 15} \\ 1965 \end{array}$$

from which a new bearing tree

A white fir, 15 ins. diam., bears S. 76° W.,
 $58\frac{1}{2}$ lks. dist., mkd. $\frac{1}{4}$ S15 BT.

Deposit T iron alongside the iron post.

N. $88^{\circ} 12'$ W., beginning new measurement.

Descend 30 ft. over SW. slope.

- 8.25 Ravine, drains S.; asc. 45 ft. over SE. slope.
11.60 Spur, slopes S.; desc. 70 ft. over SW. slope.
15.05 Creek, 1 lk. wide, course S.; asc. 500 ft. over SE. slope.
38.91 The cor. of secs. 9, 10, 15, and 16.

Land, mountainous.

Soil, rocky clay loam.

Timber, fir, hemlock, cedar, maple, madrone, dogwood, alder,
ash, yew, and chinquapin; undergrowth, vine maple, salal,
ocean spray, Oregon grape, hazel, huckleberry, blackberry,
salmonberry, poison oak, and fern.

Subdivision of Section 15, T. 22 S., R. 7 W.
Willamette Meridian, Oregon

From the $\frac{1}{4}$ sec. cor. of secs. 15 and 22.

N. $1^{\circ} 27'$ W., on the N. and S. center line of sec. 15.

Ascend 180 ft. over S. slope, through pasture land, with
scattering timber.

- 18.61 Point for the center S $1/16$ sec. cor. of sec. 15.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins.
in the ground, with brass cap mkd.

$$\begin{array}{r} C \\ S\ 1/16 \quad | \quad S\ 15 \\ C \\ 1965 \end{array}$$

from which

A fir, 22 ins. diam., bears S. 65° E., $68\frac{1}{2}$ lks.
dist., mkd. CS $1/16$ S15 BT.