

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of E. Bdy., T. 33 S., R. 5 W.

CHAINS

in a mound of stone, 3 ft. base, to top, with brass cap mkd.

COUNTY SURVEYORS OFFICE

		T 32 S		
R		1	S 31	R
5	S	1		4
W				W
		T 33 S		
		1964		

from which a bearing tree mkd. by Nicklin and Chapman:

A Douglas-fir, 18 ins. diam., bears N. 47° E.
32 lks. dist., mkd. S2 4W S31 on an opened
blaze.

and a bearing tree not of record.

A Douglas-fir, 10 ins. diam., bears N. 28° W.,
20 lks. dist., mkd. T33S R5W S1 BT on an opened
blaze.

and new bearing trees

A Douglas-fir, 8 ins. diam., bears N. 72° E.,
62 lks. dist., mkd. T32S R4W S31 BT.

A Douglas-fir, 10 ins. diam., bears N. 39° W.,
22 lks. dist., mkd. T33S R5W S1 BT.

Thence N. 0° 50' W., along the E. bdy. of sec. 1.

Descend 205 ft. over N. slope, through heavy timber
and light undergrowth.6.70 The cor. of Tps. 32 and 33 S., R. 5 W., only, on the
W. bdy. of sec. 31, T. 32 S., R. 4 W.

Land, mountainous.

Soil, rocky clay.

Timber, Douglas fir, ponderosa pine, and incense cedar;
undergrowth, arrowwood and conifer reproduction.

The following field notes describe the remonumentation
of certain original corner points of township 33 south,
range 5 west, of the Willamette Meridian, Oregon, as
provided for in the General Special Instructions, Group
No. 350, Oregon, dated May 3, 1957, "Investigation of
Collateral or Physical Evidence of Corner positions and
Accessories, followed by Remonumentation of Corner
Points, With New Accessories When Needed."

The history of original corner establishments is
referred to at appropriate places in the field notes
of the remonumentation.

South Boundary, T. 33 S., R. 5 W.
Willamette Meridian, Oregon

(Remonumenting a corner established by Sewall Truax,
in 1857 and rehabilitated by Edward F. Sharp, in 1894)

The corner of secs. 5, 6, 31, and 32, on the S bdy. of
the tp., monumented with a basalt stone, 12 x 10 x 8 ins.