

County Surveyor's Record, Douglas County, Oregon

Remonumentation of Certain Original Corner Points,
T. 33 S., R. 5 W., Willamette Meridian, Oregon

CHAINS

firmly set, 8 ins. in the ground, mkd. with 5 notches on the E. and 1 notch on the W. edge, from which the original bearing trees:

A madrone, 22 ins. diam., bears N. 63° E., 26 lks. dist., with partly opened blaze, no marks visible, (Record, 25 lks.)

A rotted black oak snag, 14 ins. diam., bears S. 37° E., 32 lks. dist., with axe marks visible on rotted blaze.

A rotted black oak snag, 16 ins. diam., bears S. 57° W., 39 lks. dist., with rottd. blaze, no marks visible. (Record, 41 lks.)

A madrone, 22 ins. diam., bears N. $28\frac{1}{2}^{\circ}$ W., 57 lks. dist., with cribe marks S visible on partly opened blaze.

At the corner point

Set an iron post, 28 ins long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 33 S R 5 W			
S	31		S 32
S	6		S 5
1967			

from which new bearing trees

A fir, 21 ins. diam., bears S. $3\frac{1}{2}^{\circ}$ E., 39 lks. dist., mkd. T32S R5W S5 BT.

A fir, 7 ins. diam., bears S. 47° W., 69 lks. dist., mkd. T34S R5W S6 BT.

Deposit corner stone alongside iron post.

The $\frac{1}{4}$ sec. cor. of secs. 25 and 36 determined at record bearing and distance from the original bearing trees:

A rotted fir stump, size indeterminate, bears N. $21\frac{1}{2}^{\circ}$ E., 63 lks. dist., no marks visible.

A down and rotted fir, 14 ins. diam., bears S. 11° W., 24 lks. dist., with scribe marks $\frac{1}{4}$ visible on opened blaze.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 33 S R 5 W			
$\frac{1}{4}$	S 25		
	S 36		
1966			

from which new bearing trees

A fir, 7 ins. diam., bears N. 36° E., 131 lks. dist., mkd. $\frac{1}{4}$ S25 BT.

A fir, 14 ins. diam., bears S. 83° W., 12 lks. dist., mkd. $\frac{1}{4}$ S36 BT.