

13987 County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 32 S., R. 6 W.

CHAINS

From which the original bearing trees

A fir snag, 20 ins. diam., bears S. 70° E.,  
16 lks, dist., with scribe marks BT visible  
on opened blaze.

A fir snag, 36 ins. diam., bears N. 10° W.,  
31 lks, dist., no marks visible.

and bearing trees marked by Byron

A cedar, 18 ins. diam., bears S. 52° E.,  
56 lks. dist., with a healed blaze.

A fir, 16 ins. diam., bears S. 86° W.,  
41 lks. dist., with a healed blaze.

Add the marks BLM 1966 to brass cap.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, chinquapin, and madrone; undergrowth,  
poison oak, vine maple, hazel, salal, and Oregon grape.

From the cor. of secs. 14, 15, 22 and 23.

S. 89° 42' W., bet. secs. 15 and 22.

Descend 140 ft. over SW. slope, changing to S. slope, through  
heavy timber and dense undergrowth.

14.90 Spur ridge, bears SW. and NE., slopes SW.; desc. 170 ft.  
over NW. slope.

20.89 Point for the E 1/16 sec. cor. of secs. 15 and 22.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins.  
in the ground, with brass cap mkd.

E 1/16  $\frac{S\ 15}{S\ 22}$   
1966

From which

A fir, 36 ins. diam., bears N. 13° E., 18 lks.  
dist., mkd. E 1/16 S15 BT.

A chinquapin, 12 ins. diam., bears S. 45° W.,  
21 lks, dist., mkd. E 1/16 S22 BT.

Descend 140 ft. over NW. slope.

29.40 Creek, 3 lks. wide, course SW.: asc. 5 ft. over SE. slope.  
changing to W. slope.

35.70 Gravelled road, 30 lks. wide, bears N. and S.

38.40 Wood Creek, 20 lks, wide, course S. 5° W.; asc. 20 ft.  
over E. slope.

41.78 The 1/4 sec. cor. of secs. 15 and 22, monumented with a yew post,  
3 x 3 ins. sq., firmly set, protruding 18 ins. above the  
ground, from which the original bearing trees.: