

13993 County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 32 S., R. 6 W.

CHAINS

1.00 Top of ascent, slopes W.; desc. 50 ft. over NW. slope.

11.10 Creek, 20 lks. wide, course S. 30° W.; asc. 165 ft. over SE. slope.

11.90 Gravelled road, 30 lks. wide, bears N. 25° E. and S. 25° W.

19.92 Point for the S 1/16 sec. cor. of secs. 9 and 10.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

S 1/16
S 9/S 10
1967

from which

A chinquapin, 7 ins. diam., bears N. 34° E., 15 lks. dist., mkd. S 1/16 S10 BT.

A madrone, 6 ins. diam., bears S. 65° W., 13½ lks. dist., mkd. S 1/16 S9 BT.

Ascend 400 ft. over SE. slope.

39.84 The ¼ sec. cor. of secs. 9 and 10, monumented with a cedar post, 4 x 4 ins. sq., firmly set, protruding 24 ins. above the ground, from which the original bearing trees:

The stump hole of a down cedar, 24 ins. diam., bears N. 50° E., 3 lks. dist., no marks visible on tree.

The stump of a down madrone, 14 ins. diam., bears N. 80° W., 23 lks. dist., with illegible scribe marks visible in negative on overgrowth of the tree. (Record, laurel)

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 32 S R 6 W
¼
S 9/S 10
1966

from which new bearing trees

A fir, 6 ins. diam., bears S. 61° E., 46 lks. dist., mkd. ¼ S10 BT.

A cedar, 8 ins. diam., bears S. 33° W., 36 lks. dist., mkd. ¼ S9 BT.

Reset cedar post alongside iron post.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, chinquapin, and madrone; undergrowth, poison oak, vine maple, hazel blackberry, salal, and Oregon grape.

Subdivision of Sec. 15, T. 32 S., R. 6 W.,
Willamette Meridian, Oregon

NOT RECORDED
11/15/67