

Dependent Resurvey, Portion of Subdivisional Lines, T. 29 S., R. 9 W.

CHAINS

Timber, fir, hemlock, cedar, oak, alder, maple, madrone, chinquapin, and yew; undergrowth, vine maple, poison oak, dalal, ocean spray, fern, hazel, blackberry, and huckleberry.

From the cor. of secs. 23, 24, 25, and 26, perpetuated and recorded by J. W. Cole, Deputy County Surveyor, in 1920, monumented with an iron pipe, 1½ ins. diam., firmly set, extending 18 ins. above the ground. Cole did not state how he determined this corner point, but he does state that no evidence of the original corner was found. This corner position is very near the proportionate position, and is therefore accepted.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 29 S R 9 W
 $\frac{S\ 23}{S\ 26} | \frac{S\ 24}{S\ 25}$
 1966

from which

A fir, 35 ins. diam., bears N. 28°E., 124 lks. dist., mkd. T29S R9W S24 BT.

A fir, 25 ins. diam., bears S. 15° E., 23½lks. dist., mkd. T29S R9W S25 BT.

A fir, 22 ins. diam., bears S. 35° W., 26 lks. dist., mkd. T29S R9W S26 BT.

No bearing tree available to the NW. within limits.

Reset iron pipe alongside iron post.

From this point the SE. corner of a wood frame house, bears N. 24°E., 0.25 chs. dist., dimensions 28½ x 39 ft., long side bears N. and S.

From this same point the cor. of secs. 25, 26, 35, and 36, bears South, 79.96 chs. dist., previously described.

From this same point the ¼ sec. cor. of secs. 24 and 25, bears N. 89° 33' E., 39.87 chs. dist., perpetuated and recorded by J. W. Cole, Deputy County Surveyor, in 1920, from an original bearing tree which is no longer in existence, monumented with an iron pipe, 2 ins. diam., firmly set, extending 2 ins. above the ground

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 29 S R 9 W
 $\frac{1}{4} \frac{S\ 24}{S\ 25}$
 1966

from which

A forked ash, 21 ins. diam., bears N. 2° E., 334 lks. dist., mkd. ¼ S24 BT.