

14008 County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 29 S., R. 9 W.

CHAINS	
	<p>No other bearing tree available within limits.</p> <p>Reset iron pipe alongside the iron post.</p> <p>Corner is located in a N. and S. fence line.</p> <p>N. 0° 05' E., bet. secs. 23 and 24.</p> <p>Descend 55 ft. over NE. slope, through open pasture land.</p>
0.23	Intersect S. side of wood frame house, dimensions 28½ x 39 ft., long side bears N. and S., SE. corner bears East, 10 lks. dist.
0.82	North side of house.
2.30	Dirt road, 15 lks. wide, bears N. 80° W. and S. 80° E.
3.79	Barbed wire fence, bears E. and W.
19.98	<p>Point for the S 1/16 sec. cor. of secs. 23 and 24.</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">S 1/16 S 23/S 24 1966</p> <p>from which</p> <p>An oak, 14 ins. diam., bears S. 46½° W., 488 lks. dist., mkd. S 1/16 S23 BT.</p> <p>No other bearing tree available within limits.</p> <p>The corner is located 18 lks. East of a N. and S. fence line.</p> <p>Descend 25 ft. over NE. slope.</p>
25.35	Ravine, drains S. 70° E.; asc. 85 ft. over S. slope, changing to SE. slope.
39.94	Barbed wire fence, bears E. and W.
39.96	<p>The ¼ sec. cor. of secs. 23 and 24, determined at record bearing and distance from the original bearing trees:</p> <p>A down oak, 25 ins. diam., bears S. 8° E., 1516 lks. dist., with scribe marks ¼ S visible on opened blaze.</p> <p>An oak, 34 ins. diam., bears S. 5° W., 1409 lks. dist., no marks visible.</p> <p>At the corner point</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T 29 S R 9 W ¼ S 23/S 24 1966</p> <p>from which a new bearing tree</p>