

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines. T. 29 S., R. 9 W.

CHAINS

A fir, 9 ins. diam., bears N. 75°W., 45½ lks.  
dist., mkd. ¼ S1 BT.

A fir, 11 ins. diam., bears S. 30° W., 11½ lks.  
dist., mkd. ¼ S12 BT.

Corner is located 1 lk. South of E. and W. fence.

Ascend 145 ft. over rolling SE. slope.

40.27 Fence corner, fence lines extend S. and E.

62.30 The SE. cor. of old growth timber, edges bear generally N. and W.; continue along N. edge of logged area.

74.50 Top of ascent, slopes S.; desc. 85 ft. over SW. Slope.

80.34 The cor. of secs. 1, 2, 11, and 12.

Land, rolling hills.

Soil, rocky clay loam.

Timber, fir, hemlock, cedar, oak, alder, maple, madrone, chinquapin, and yew; undergrowth, vine maple, poison oak, salal, ocean spray, fern, hazel, blackberry, and huckleberry.

N. 0° 48' E., bet. secs. 1 and 2.

Ascend 115 ft. over SW. slope, along the E. edge of logged area, through heavy timber and dense undergrowth.

8.00 Top of ascent, slopes W.; desc. 90 ft. over NW. slope.

23.30 Creek, 1 lk. wide, course S. 30° W.; asc. 70 ft. over SE. slope.

32.30 Same creek, course S. 30°E.; asc. 75 ft. over SW. slope.

39.50 Same creek, cours S. 30° W.; asc. 10 ft. over SE. slope.

40.11 Point for the ¼ sec. cor. of secs. 1 and 2, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 23 ins. in the ground, with brass cap mkd.

T 29 S R 9 W

¼  
S 2/S 1  
1966

from which

A fir, 8 ins. diam., bears S. 38° E., 28½ lks.  
dist., mkd. ¼ S1 BT.

A fir, 7 ins. diam., bears N. 51° W., 24 lks.  
dist., mkd. ¼ S2 BT.

Corner is located at the NE. cor. of logged area, edges bear generally S. and W.

Ascend 480 ft. over broken SE. slope, through heavy timber and dense undergrowth.