

Dependent Resurvey, Portion of Subdivisional Lines, T. 29 S., R. 9 W.

CHAINS

A fir, 9 ins. diam., bears N. 27°W., 170 lks. dist., with healed blaze.

A fir, 22 ins. diam., bears S. 29½° W., 222 lks. dist., with healed double blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 29 S R 9 W  
 $\frac{1}{4}$  S 23  
          
 S 26  
 1966

Reset iron axle alongside the iron post.

Corner is located at the intersection of fences extending N., S., E., and W.

N. 89° 23' W., beginning new measurement.

Leave pasture land; enter logged area with scattering timber and dense undergrowth, edge bears N. and S.; asc. 3 ft. over E. slope, along irregular E. and W. fence.

1.30 Top of ascent, slopes S.; desc. 20 ft. over W. slope.

6.65 Creek, 4 lks. wide, course SE.: asc. 185 ft. over E. slope.

17.00 Dirt road, 25 lks. wide, bears N. 5° W. and S. 5° E.

27.70 Top of ascent, slopes N.; desc. 110 ft. over W. slope.

28.70 The SE. cor. of old growth timber, edges bear N. and W., continue along N. edge of logged area.

40.35 The cor. of secs. 22, 23, 26, and 27, perpetuated and recorded by J. W. Byron, Deputy County Surveyor, in 1959, monumented with an iron pipe, 1 in. diam., firmly set, extending 14 ins. above the ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE  
 T 29 S R 9 W  
S 22/S 23  
S 27/S 26  
 1959

from which the remaining original bearing trees

A white fir, 25 ins. diam., bears N. 50° E., 27 lks. dist., with healed blaze. (Record, fir.)

A down fir, 20 ins. diam., bears N. 50° W., 36 lks. dist., with scribe marks BT visible on opened blaze.

and a bearing tree marked by William Porter in 1907

A stump hole with fir roots, bears S. 50° E., 52 lks. dist.

and bearing trees marked by Byron