

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of S. Bdy., T. 29 S., R. 3 W.

CHAINS

dist., bark scribed $\frac{1}{4}$ S BT. (Record,
S. 40° W., 23 lks.)

and a bearing tree mkd. by Bushey in 1893

A cedar, 27 ins. diam., bears S. 36° E., 54 lks.
dist., mkd. with a healed blaze.

and a bearing tree mkd. by J. W. Byron, Deputy County
Surveyor, in 1962,

A fir, 18 ins. diam., bears N. 30°W., 87 lks.
dist., mkd. with a healed blaze.

From this point a witness corner established and recorded
by J. W. Byron, Deputy County Surveyor, in 1962, bears
N. 13° W., 0.06 chs. dist., monumented with an iron post,
1 in. diam, firmly set, extending 16 ins. above ground, with
brass cap mkd.

COUNTY SURVEYORS OFFICE

T 29 S R 3 W

South

 $\frac{1}{4}$ S 34

W C

T 30 S

1962

N. 89° 55' W., on the S. bdy. of sec. 34, marking and
blazing the true line.

Descend 25 ft. over SW. slope, through heavy timber and dense
undergrowth, along S. edge of logged area.

4.30 Ridge, bears N. 60°E. and S. 30° W., and dirt road,
15 lks. wide, bears N., curving to NE., and S., curving
to SW.; desc. 365 ft. over NW. slope.

21.80 Spring seepage, drains NW.: asc. 10 ft. along broken N.
slope.

32.70 Spur, slopes N. 55° W.; desc. 165 ft. over W. slope.

38.17 The cor. of secs. 33 and 34 only, restored by the method
of broken boundaries; there is no remaining evidence of the
original corner.

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 34 ins. in
the ground, with brass cap mkd.

T 29 S R 3 W

S 33/S34

S 3

T 30 S R 3 W

1967

from which

A fir, 17 ins. diam., bears N. 26 $\frac{3}{4}$ ° E., 87 lks.
dist., mkd. T29S R 3W S34 BT.

A fir, 15 ins. diam., bears N. 19 $\frac{1}{4}$ ° W., 101 lks.
dist., mkd. T29S R3W S33 BT.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, madrone, oak, chinquapin, and maple,
undergrowth, young timber, fern, salal, huckleberry, Oregon
grape, vine maple, and blackberry.