

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 29 S., R. 3 W.

CHAINS	
	<p>A madrone, 33 ins. diam., bears N. 5°W., 28 lks. dist., with healed blaze.</p> <p>At the corner point</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T 29 S R 3 W ¼ S 9/S 10 1966</p> <p>from which a new bearing tree</p> <p>A fir, 8 ins. diam., bears S. 35° E., 31 lks. dist. mkd. ¼ S10 BT.</p> <hr/> <p>N. 1° 06'E., beginning new measurement.</p> <p>Ascend 10 ft. over SE. slope.</p>
0.50	Top of ascent, slopes E.; desc. 20 ft. over NE. slope.
2.00	Ravine, drains E.; asc. 85 ft. over SE. slope.
6.80	Spur, slopes E.; desc. 65 ft. over broken NE. slope.
14.50	Ravine, drains S. 30°E.; asc. 65 ft. over S. slope.
20.80	Spur, slopes E.; desc. 100 ft. over broken NE. slope, changing to E. slope.
37.89	<p>The cor. of secs. 3, 4, 9 and 10, monumented with an iron pipe, 1 in. diam., firmly set, extending 12 ins. above ground, with brass cap marked and witnessed as described in the official record of the 1964-65 resurvey.</p> <p>Land, mountainous. Soil, rocky clay loam. Timber, fir, cedar, madrone, oak, pine, chinquapin, maple, dogwood, yew, and alder; undergrowth, vine maple, poison oak, salal, fern, hazel, ocean spray, Oregon grape, huckleberry, blackberry, rhododendron, and manzanita.</p> <hr/> <p>From the cor. of secs 4, 5, 32, and 33, on the S. bdy. of the Tp.</p> <p>N. 0° 03' W., bet. secs. 32 and 33.</p> <p>Ascend 15 ft. over SE. slope, through scattering timber and light undergrowth, along W. edge of open pasture.</p>
1.80	Creek, 1 lk. wide, course SE.: asc. 150 ft. over SE. slope.
13.70	Wire fence. bears N. 30°E. and S. 30°W.
20.04	<p>Point for the S 1/16 sec. cor. of secs. 32 and 33.</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">S 1/16 S 32/S 33 1967</p>