

Dependent Resurvey, Portion of Subdivisional Lines, T. 29 S., R. 3 W.

CHAINS	
1.00	Abandoned dirt road, 15 lks. wide, bears NW. and SE.
5.15	Gravelled road, 30 lks. wide, bears NE. and SW.
6.00	Creek, 3 lks. wide, course NW.; desc. 35 ft. over creek bottom.
9.10	Board and wire fence, bears N. 85°E. and S. 85°W.; enter open pasture.
18.20	Board fence, bears N. 30°E. and S. 30°W.; enter cultivated field.
20.42	Point for the E 1/16 sec. cor. of secs. 28 and 33. Set an iron post, 28 ins. long, 2½ ins. diam., 18 ins. in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd. <div style="text-align: center;"> $\begin{array}{r} \text{E } 1/16 \text{ } \frac{\text{S } 28}{\text{S } 33} \\ 1967 \end{array}$ </div> from which A fir, 8 ins. diam., bears N. 74½°E., 404 lks. dist., mkd. E 1/16 S28 BT. A fir, 32 ins. diam., bears S. 66½° E., 303 lks. dist., mkd. E 1/16 S33 BT. Descend 15 ft. over creek bottom.
22.60	Wire fence, bears N. 20° E. and S. 30°W.; enter pasture.
26.15	Days Creek, 10 lks. wide, course S. 20° W., asc. 85 ft. over gradual SE. slope.
40.76	The cor. of wire fences extending N., S. 30°E. and W.; enter heavy young timber and dense undergrowth.
40.84	The ¼ sec. cor. of secs. 28 and 33, determined in the center of the stump hole of the original corner tree, an uprooted cedar lying alongside, 6 ins. diam., with scribe marks ¼ S visible on N. and ¼ S visible on S. side on partially healed blazes, from which the original bearing trees: A fir root crown, size indeterminate, bears N. 75°W., 10 lks. dist., with no marks remaining. A sawed fir stump, 32 ins. diam., bears S. 70° E., 12 lks. dist., with illegible scribe marks visible on remaining portion of opened blaze. and bearing trees mkd. by J. W. Byron, Deputy County Surveyor, in 1959 A fir, 15 ins. diam., bears N. 9° W., 82 lks. dist., with a healed blaze. A fir, 15 ins. diam., bears S. 28½° W., 42 lks. dist., with a healed double blaze. At the corner point Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in