

County Surveyor's Record, Douglas County, Oregon

14094

Subdivision of Part of T. 30 S., R. 1 E.

CHAINS	
	<p>A fir, 45 ins. diam., bears N.44°W., 92 lks. dist., mkd. $\frac{1}{4}$ S 24 B T.</p> <p>A fir, 45 ins. diam., bears S.30°W., 178 lks. dist., mkd. $\frac{1}{4}$ S 25 B T.</p> <p>Asc. 10 ft. over NE. slope.</p>
38.60	Top of ascent on N. slope; desc. 15 ft. over NW. slope.
41.35	Head of draw, drains N.; asc. 190 ft. over NE. slope.
49.85	Spur, slopes NW.; desc. 800 ft. over W. slope, changing to SW. slope.
63.00	Enter heavy timber, bears N. and S.
71.65	Deadhorse Creek, 25 lks. wide, course NW.; asc. 195 ft. over NE. slope.
78.11	The cor. of secs. 23, 24, 25, and 26.
	<p>Land, mountainous. Soil, sandy loam and rocky; 3rd and 4th rate. Timber, fir, hemlock, cedar, pine, and yew. Undergrowth, vinemaple, rhododendron, 2nd growth, huckleberry, serviceberry, manzanita, slickleaf, chinquapin, madrona, and salal.</p>
	<p>N.0° 01' W., ber. secs. 23 and 24.</p> <p>Desc. 400 ft. over NE. slope, through heavy timber and dense undergrowth.</p>
34.35	Squaw Creek, 50 lks. wide, course N.75°W.; asc 40 ft. over SW. slope.
40.00	<p>Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.</p> <div style="text-align: center;"> $\frac{1}{4}$ S23 S24 1937 </div> <p style="text-align: right;">from which</p>
	<p>A fir, 28 ins. diam., bears S.62°E., 32 lks. dist., mkd. $\frac{1}{4}$ S 24 B T.</p> <p>A fir, 8 ins. diam., bears N.37°W., 19 lks. dist., mkd. $\frac{1}{4}$ S 23 B T.</p>
41.45	<p>Along W. slope. Small draw, drains W.; asc. 650 ft. over broken SW. slope.</p>
62.55	Head of draw, drains SW.
78.00	Head of draw, drains SW.
80.00	<p>Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for cor. of secs. 13, 14, 23, and 24, with brass cap mkd.</p> <div style="text-align: center;"> T30S R1E S14 S13 S23 S24 1937 </div> <p style="text-align: right;">from which</p>