

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the W. Bdy., T. 22 S., R. 8 W.

## CHAINS

An alder, 8 ins. diam., bears N. 65° W., 66 lks.  
dist., mkd.  $\frac{1}{4}$  S25 BT.

A maple, 20 ins. diam., bears S. 13° W., 57 lks.  
dist., mkd.  $\frac{1}{4}$  S25 BT.

Corner falls on S. bank of creek.

Descend 1 ft. over bank of creek.

45.30 Creek, 5 lks. wide, course W.; asc. 414 ft. over SE. slope.

46.30 Graveled road, 30 lks. wide, bears E. and W.

65.50 Spur, slopes W.; desc. 340 ft. over NW. slope.

80.15 Creek, 5 lks. wide, course W.; desc. 23 ft. over NW. slope.

81.45 Creek, 3 lks. wide, course S. 40° W.; asc. 72 ft. over  
S. slope.

84.20 Point for the cor. of secs. 19, 24, 25, and 30, at  
proportionate distance; the original corner.

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$  ins. diam., 24 ins.  
in the ground, with brass cap mkd.

T 22 S  
R 9 W R 8 W  
S 24 | S 19  
S 25 | S 30  
1965

from which

A fir, 8 ins. diam., bears N. 76 $\frac{1}{2}$ ° E., 72 lks.  
dist., mkd. T22S R8 W S19 BT.

A fir, 18 ins. diam., bears S. 41° E., 37 lks.  
dist., mkd. T22S R8W S30 BT.

A fir, 14 ins. diam., bears S. 38° W., 22 $\frac{1}{2}$  lks.  
dist., mkd. T22S R9W S25 BT.

A fir, 16 ins. diam., bears N. 19° W., 21 lks.  
dist., mkd. T22S R9W S24 BT.

Land, mountainous.

Soil, sandy clay loam.

Timber, fir, hemlock, cedar, alder, maple, chinquapin,  
willow, myrtle, and madrone; undergrowth, vinemaple,  
hazel, arrowwood, salmonberry, huckleberry, salal,  
poison oak, and fern.

N. 0° 28' E., bet. secs. 19 and 24, on the W. bdy. of the Tp.

Ascend 126 ft. over general S. slope, through heavy  
timber and dense undergrowth.

13.70 Top of ascent, slopes W.; desc. 61 ft. over NW. slope.

19.90 Creek, 2 lks. wide, course S. 40° W.; asc. 209 ft. over  
SE. slope.