

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 22 S., R. 8 W.

CHAINS

$$\frac{1}{4}$$

S 10 S 11  
T 22 S R 8 W  
1967

Deposit the corner stone alongside the iron post.

---

N. 0° 40' E., beginning new measurement.

Ascend 5 ft. across open fields.

1.30 Hard surfaced road, 20 lks. wide, bears N. 80° E. and S. 80° W.

8.55 Paradise Creek, 20 lks. wide, course S. 50° W.

13.20 Same creek, 20 lks. wide course S. 50° E.; asc. 50 ft. across open field.

20.10 Point for the N 1/16 sec. cor. of secs. 10 and 11.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

N 1/16  
S 10 | S 11  
1967

from which

A fir, 8 ins. diam., bears S. 72½° E., 227 lks. dist., mkd. N 1/16 S11 BT.

A fir, 5 ins. diam., bears N. 5° W., 278 lks. dist., mkd. N 1/16 S10 BT.

Ascend 155 ft. over SW. slope, through scattering young timber.

30.90 Top of ascent, slopes W.; desc. 40 ft. over NW. slope.

33.00 Creek, 1 lk. wide, course S. 40° W.; asc. 75 ft. over SW. slope.

38.50 Top of ascent, slopes W. p desc. 15 ft. over NW. slope.

40.20 The cor. of secs. 2, 3, 10, and 11, monumented with an iron post, 1½ ins. diam., firmly set, projecting 8 ins. above ground, with brass cap marked and witnessed as described in the official record of the 1963-65 dependent resurvey.

Land, mountainous.

Soil, sandy clay loam.

Timber, fir, hemlock, cedar, oak, maple, chinquapin, and alder; undergrowth, vinemaple, arrowwood, hazel, huckleberry, salmonberry, thimbleberry, salal, and fern.

---

From the cor. of secs. 1, 2, 11, and 12.

N. 89° 24' W., bet. secs. 2 and 11.

Ascend 140 ft. over NE. slope, through dense brush across old logged area.

5.50 Top of ascent, slopes N.; desc. 90 ft. over NW. slope.