

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 29, T. 22 S., R. 8 W.

CHAINS	6 ins. above ground, with brass cap, marked and witnessed as described in the official record of the 1960 dependent resurvey.
	N. 0° 46' W., along the N. and S. center line of the SW $\frac{1}{4}$ of sec. 29.
	Ascend 78 ft. over SE. slope. through scattering timber and dense undergrowth.
6.45	Spur, slopes N. 60° E.; desc. 52 ft. over broken NE. slope.
12.80	Bottom of descent, slopes E.; asc. 20 ft. over SE. slope.
15.45	Spur. slopes E.; desc. 104 ft. over NE. slope.
19.62	Point for the SW 1/16 sec. cor. of sec. 29, at intersection with the E. and W. center line of the SW $\frac{1}{4}$.
	Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam, 24 ins. in the ground, with brass cap mkd.
	SW 1/16 S 29 1965
	from which
	A fir, 20 ins. diam., bears S. 83 $\frac{1}{2}$ ° E., 99 lks. dist., mkd. SW 1/16 S29 BT.
	A maple, 13 ins. diam., bears N. 81 $\frac{1}{2}$ ° W., 67 $\frac{1}{2}$ lks. dist., mkd. SW 1/16 S29 BT.
	Descend 141 ft. over NE. slope.
22.45	Creek, 2 lks. wide, course S. 85° E.; asc. 188 ft. over SE. slope.
35.80	Spur, slopes S. 50° E.; desc. 102 ft. over NE. slope.
37.90	Bottom of descent, slopes E.; asc. 62 ft. over SE. slope.
39.32	The center W 1/16 sec. cor. of sec. 29.
	From the center S 1/16 sec. cor. of sec. 29.
	S. 89° 19' W., along the E. and W. center line of the SW $\frac{1}{4}$ of sec. 29.
	Ascend 63 ft. over E. slope. through scattering timber and dense undergrowth.
6.40	Top of ascent, slopes S.; desc. 35 ft. over SW. slope.
8.40	Graveled road, 20 lks. wide, bears N. 35° E. and S. 35° W.
9.95	Creek, 2 lks. wide, course S, 60° E.; asc. 189 ft. over NE. slope.
19.32	The SW. 1/16 sec. cor. of sec. 29.
	Ascend 347 ft. over NE. slope.
38.66	The S1/16 sec. cor. of secs. 29 and 30.