

County Surveyor's Record, Douglas County, Oregon

Remonumentation of Certain Original Corner Points,
T. 20 S., R. 7 W., Willamette Meridian, Oregon

CHAINS

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T 20 S R 7 W
 $\frac{1}{4}$
 S 6 | S 5
 1967

Set a steel fence post alongside the iron post.

General Description

The portion of township 20 south, range 7 west, covered by this resurvey is located about 16 miles northwest of Drain, Oregon. The land is extremely mountainous and broken with numerous small streams found on either side of the ridge dividing South Sister Creek and Smith River drainage. The elevation ranges from about 800 feet above sea level near the corner of sections 19, 20, 29, and 30, to about 1600 feet above sea level near the center of section 30. The soil varies from rocky clay at higher elevations to sandy clay in the creek bottoms, with sandstone outcroppings on the steep slopes.

The lines surveyed are all located in the area burned over by the Oxbow Ridge fire which occurred in August, 1966. Except for the burned over logged portions, the area is covered with burned fir, hemlock, cedar, maple, alder, yew, dogwood, and chinquapin. The undergrowth has been burned off except for scattering patches of vine maple, salal, salmonberry, huckleberry, hazel, Oregon grape, and fern. Numerous logging roads are located throughout the area. Several abandoned trails were noted which cross the area.

No evidence of mineral deposits were noted along the lines surveyed.

Several readings along the lines surveyed give a mean magnetic declination of 20° 00' East.