

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 21 S., R. 7 W.

CHAINS

T 21 S R 7 W
 S 18 | S 17
 S 19 | S 20
 1967

from which

A hemlock, 13 ins. diam., bears N. 26° E., 39 lks. dist., mkd. T21S R7W S17 BT.

A fir, 38 ins. diam., bears S 73° E., 113 lks. dist., mkd. T21S R7W S20 BT.

A hemlock, 12 ins. diam., bears S. 34° W., 21 lks. dist., mkd. T21S R7W S19 BT

A hemlock, 15 ins. diam., bears N. 29° W., 58 lks. dist., mkd. T21S R7W S18 BT.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, maple, chinquapin, madrone, dogwood and yew; undergrowth, salal, Oregon grape, hazel, vine maple, ceanothus, huckleberry, salmonberry, vines and ferns.

From the cor. of secs. 16, 17, 20 and 21, monumented with an iron post, 2½ ins. diam., firmly set, protruding 5 ins. above ground, with brass cap marked and witnessed as described in the official record of the 1964 dependent resurvey.

N. 89° 39' W., bet. secs. 17 and 20.

Descend 160 ft. over SW. slope, through heavy timber and dense undergrowth.

15.50 Creek, 2 lks. wide, course S. 60° W.; asc. 15 ft. over SE. slope.

20.06 Set an iron post, 28 ins. long, 2½ ins. diam., 21 ins. in the ground, with brass cap marked

E 1/16 S 17
 S 20
 1967

from which

A hemlock, 26 ins. diam., bears N. 44½° E., 13 lks. dist., mkd. E 1/16 S17 BT.

A hemlock, 21 ins. diam., bears S. 56½° E., 29 lks. dist., mkd. E. 1/16 S20 BT.

The corner is located on a spur, slopes S.

Descend 175 ft. over broken SW. slope.

40.12 The ¼ sec. cor. of secs. 17 and 20, determined at record bearing and distance from the remaining original bearing tree:

A cedar snag, 50 ins. diam., bears South, 6 lks. dist., with no marks visible on rotted blaze.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 21 S R 7 W
 ¼ S 17
 S 20
 1967