

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional lines, T. 21 S., R. 7 W.

CHAINS

- 1.70 Paved road, 30 lks. wide, bears NW. and SE.
- 15.00 Bottom of descent, slopes S.; asc. 35 ft. over SE. slope.
- 18.60 Enter logged area, edge bears N. and S.
- 22.60 Spur, slopes S.; des. 120 ft. over SW. slope.
- 29.10 Wet ravine, drains S. 40 W.; desc. 110 ft. over SW. slope.
- 39.36 The $\frac{1}{4}$ sec. cor. of secs. 7 and 18, determined at record bearing and distance from the remaining original bearing tree:
- A cedar, 37 ins. diam., bears N. 40° E., 42 lks. dist., with scribe marks $\frac{1}{4}$ S visible on opened blaze.
- At the corner point
- Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 21 ins. in the ground, with brass cap mkd.
- T 21 S R 7 W

$\frac{1}{4}$	S 7
	S 18

1967
- from which
- An alder, 8 ins. diam., bears S. 47° W., 72 lks. dist., mkd. $\frac{1}{4}$ S18 BT.
-
- N. 88° 36' W., beginning new measurement.
- Descend 35 ft. over SW. slope.
- 9.00 Halfway Creek, 15 lks. wide, course N. 30° W.; asc. 335 ft. over NE. slope.
- 17.40 Spur, slopes N.; desc. 140 ft. over NW. slope.
- 21.60 Ravine, drains N.; asc. 100 ft. over NE. slope.
- 26.80 Spur, slopes N.; enter timber, edge bears N. and S.; desc. 245 ft. over NW. slope.
- 35.63 The cor. of secs. 7, 12, 13, and 18, on the W. Bdy. of the Tp., monumented with an iron post, 2 ins. diam., firmly set, protruding 5 ins. above ground, with brass cap marked and witnessed as described in the official record, of the 1952-54 dependent resurvey.
- Land, mountainous.
Soil, rocky clay.
Timber, fir, hemlock, cedar, maple, alder, dogwood and chinquapin; undergrowth, salal, rhododendron, vine maple, hazel, huckleberry, vines and ferns.

GENERAL DESCRIPTION

The lands included in the notes of the foregoing resurvey are located about 6 miles north of Elkton, Oregon. Elevations range from about 1440 feet above sea level near the $\frac{1}{4}$ section corner of sections 18 and 19 to about 450 feet above sea level where Paradise Creek crosses the line between sections 19 and 30. The topography in the area is extremely broken and mountainous with soil consisting of rocky clay.