

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 21 S., R. 9 W.

CHAINS

and new bearing trees

A fir, 4 ins. diam., bears S. 67° E., 30 lks. dist., mkd. $\frac{1}{4}$ S23 BT.A fir, 5 ins. diam., bears S. 75° W., 35 lks. dist., mkd. $\frac{1}{4}$ S22 BT.

N. 1° 07' E., bet. secs. 22 and 23.

Ascend 255 ft. over SW. slope, through scattering timber and dense undergrowth.

10.30 Spur, slopes S. 55° W.; desc. 170 ft. over NW. slope.

16.50 Abandoned dirt road, 15 lks. wide, bears N. 55° E., and S. 55° W.

17.70 Ravine, drains W.; asc. 60 ft. over SW. slope.

21.80 Spur, slopes S. 65° W.; desc. 140 ft. over broken NW. slope.

37.00 Creek, 5 lks. wide, course S. 25° W.; asc. 50 ft. over SE. slope.

38.17 Point for the cor. of secs. 14, 15, 22, and 23, at proportionate distance, there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 25 ins. in the ground, with brass cap marked

T 21 S R 9 W
S 15 S 14
S 22 S 23
1966

from which

A fir, 10 ins. diam., bears N. 67° E., 61 lks. dist., mkd. T21S R9W S14 BT.

A fir, 12 ins. diam., bears S. 6° E., 46 lks. dist., mkd. T21S R9W S23 BT.

A fir, 8 ins. diam., bears S. 47° W., 37 lks. dist., mkd. T21S R9W S22 BT.

A fir, 5 ins. diam., bears N. 38° W., 40 lks. dist., mkd. T21S R9W S15 BT.

Land, mountainous.

Soil, sandy clay loam.

Timber, fir, hemlock, maple, and alder; undergrowth, vine maple, thimbleberry, salmonberry, huckleberry, arrowwood, hazel, rhododendron, ceanothus, Oregon grape, salal, and fern.

From the cor. of secs. 13, 14, 23, and 24.

S. 89° 53' W., bet. secs. 14 and 23.

Descend 150 ft. over NW. slope, through scattering timber and dense undergrowth.

4.00 Creek, 4 lks. wide, course S. 60° W.; asc. 110 ft. over SE. slope.

6.00 Top of ascent, slopes S.; desc. 185 ft. over SW. slope.

19.93 Point for the E 1/16 sec. cor. of secs. 14 and 23.

Set an iron post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, with brass cap marked