

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 21 S., R. 9 W.

CHAINS

from which original bearing tree:

A fir, 43 ins. diam., bears S. 41* E., 40 lks. dist., with no marks visible on partially opened blaze.

The stump hole of a fallen fir, 30 ins. diam., bears S. 40 $\frac{1}{2}$ * W., 63 lks. dist., with fragmentary scribe marks visible on partially opened blaze.

A fir stub, 40 ins. diam., bears N. 44* W., 42 lks. dist., with scribe marks T21S R visible on partially opened blaze.

and a bearing tree marked by McDonald in 1963

A fir, 42 ins. diam., bears S. 72 $\frac{1}{2}$ * E., 19 lks. dist., with scribe marks T21S R9W S11 BT visible on open blaze.

and a new bearing tree

A hemlock, 10 ins. diam., bears S. 67* W., 33 lks. dist., mkd. T21S R9W S10 BT.

No suitable trees available within limits in secs. 2 and 3.

Land, mountainous.

Soil, sandy clay loam.

Timber, fir, hemlock, cedar, maple, alder, and willow; undergrowth, huckleberry, arrowwood, hazel, vine maple, thimbleberry, salmonberry, Oregon grape, salal, and fern.

From the cor. of secs. 1, 2, 11, and 12.

S. 89* 49' w., bet. secs. 2 and 11.

Descend 175 ft. over SW. slope, through heavy timber and dense burned undergrowth.

11.50 Scare Creek, 25 lks. wide, course N.; asc. 375 ft. over SE. slope.

23.50 Spur, slopes NE.; asc. 105 ft. along N. slope.

39.72 Point for the $\frac{1}{4}$ sec. cor. of secs. 2 and 11, at proportionate distance, there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 25 ins. in the ground, with brass cap mkd.

$\frac{1}{4}$ $\frac{S\ 2}{S\ 11}$
T 21 S R 9 W
1967

from which

A hemlock, 5 ins. diam., bears N. 70* W., 87 lks. dist., mkd. $\frac{1}{4}$ S2 BT.

A fir, 6 ins. diam., bears S. 61* E., 7 lks. dist., mkd. $\frac{1}{4}$ S11 BT.

Ascend 105 ft. over NE. slope.