

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 21 S., R. 9 W.

CHAINS	
	<p>A hemlock, 22 ins. diam., bears S. 57* W., 109 lks. dist., mkd. T21S R9W S21 Bt.</p> <p>Land, mountainous. Soil, sandy clay loam. Timber, fir, hemlock, cedar, maple, alder, madrone, willow, and chinquapin; undergrowth, salmonberry, thimbleberry, vine maple, huckleberry, arrowwood hazel, poison oak, blackberry, Oregon grape, salal, and fern.</p>
	<p>From the cor. of secs. 10, 11, 14, and 15.</p> <p>N 86* 55' W., bet. secs. 10 and 15.</p> <p>Descend 215 ft. over SW. slope, through scattering timber and dense undergrowth, along the N. edge of logged area.</p> <p>9.70 Ravine drains S. 25* W.; asc. 35 ft. over SE. slope.</p> <p>12.40 Spur, slopes S.; desc. 130 ft. over SW. slope.</p> <p>16.50 Bottom of descent, slopes S.; asc. 45 ft. and over SE. slope.</p> <p>19.00 Spur, slopes S.; desc. 80 ft. over SW. slope.</p> <p>21.80 Ravine, drains S. 25* W.; asc. 85 ft. over SE. slope.</p> <p>24.70 Spur, slopes S.; desc. 50 ft. over SW. slope.</p> <p>27.80 Ravine drains S.; asc. 5 ft. over SE. slope.</p> <p>30.00 Spur, slopes S.; desc. 140 ft. over SW slope.</p> <p>39.52 The $\frac{1}{4}$ sec. cor. of secs. 10 and 15, monumented with an iron post, $2\frac{1}{2}$ ins. diam., extending 5 ins. above ground, firmly set, with brass cap marked and witnessed as described in the official record of the 1963 re- monumentation.</p>
	<hr/> <p>N. 88* 53' W., beginning new measurement.</p> <p>Descend 30 ft. over SW. slope.</p> <p>1.60 Ravine, drains S.; asc. 15 ft. over SE. slope.</p> <p>2.60 Spur, slopes S.; desc. 110 ft. over W.slope.</p> <p>4.80 Hard surfaced road, 30 lks. wide, bears N. and S.</p> <p>5.85 Vincent Creek, 15 lks. wide, course N.; asc. 350 ft. over broken SE. slope.</p> <p>32.10 Spur, slopes S.; desc. 15 ft. over SW. slope.</p> <p>35.50 Ravine, drains S.; asc. 160 ft. over SE. slope.</p> <p>39.37 The cor. of secs. 9, 10,¹⁵ and 16, monumented with an iron post, $2\frac{1}{2}$ ins. diam., extending 6 ins. above ground, firmly set, with brass cap marked and witnessed as described in the official record of the 1963 re- monumentation.</p>
	<p>Land, mountainous. Soil, sandy clay loam.</p>