

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 21 S., R. 9 W.

CHAINS

N. 88* 36' W., beginning new measurement.

Ascend 30 ft. over NE. slope.

2.60 Spur, slopes N. 30* E.; desc. 20 ft. over NW. slope.

3.50 Creek, 1 lk. wide, course N. 30* E.; asc. 280 ft. over broken NE. slope.

17.80 Spur, slopes N.; desc. 60 ft. over NW. slope.

19.815 Point for the W 1/16 sec. ^{of} secs. 3 and 10.Set an iron post, 28 ins. long, 2 $\frac{1}{8}$ ins. diam., 22 ins. in the ground, with brass cap marked
$$W \frac{1}{16} \frac{S \ 3}{S \ 10}$$

1966

from which

A fir, 10 ins. diam., bears N. 79 $\frac{1}{2}$ * E., 45 lks. dist., mkd. W 1/16 S3 BT.

A hemlock, 12 ins. diam., bears S. 35* E., 26 lks. dist., mkd. W 1/16 S10 BT.

Descend 5 ft. over NW. slope.

20.15 Ravine, drains N. 20* E.; asc. 355 ft. over NE. slope, changing to SE. slope.

33.30 Spur, slopes N. 15* E.; desc. 140 ft. over NW. slope.

37.70 Ravine, drains N. 20* E.; asc. 15 ft. along N. slope.

39.63 The cor. of secs. 3 and 10 only.

Land, mountainous.

Soil, sandy clay loam.

Timber, fir, hemlock, cedar, maple, alder, willow, and yew; undergrowth, vine maple, huckleberry, arrowwood, hazel, salmonberry, thimbleberry, blackberry, Oregon grape, salal, and fern.

N. 0* 04' W., on the W. bdy. of sec. 3.

Descend 135 ft. over N. slope, through heavy timber and dense undergrowth.

3.35 Ravine, drains E.; desc. 190 ft. over NE. slope.

14.40 Creek, 1 lk. wide, course E.; asc. 5 ft. over SE. slope.

16.85 Top of ascent, slopes E.; desc. 45 ft. over NE. slope.

21.70 Ravine, drains E.; asc. 65 ft. over SE. slope.

25.95 Spur, slopes NE.; desc. 125 ft. over NW. slope.

29.10 Creek, 2 lks. wide, course N. 25* E.; desc. 20 ft. along E. slope.

31.71 True point fro the closing cor. of secs. 4 and 9. hereinafter described.

Descend 85 ft. over N. slope.