

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 26 S., R. 2 W.

CHAINS

T 26 S R 2 W
 $\frac{S 2}{S 11} | \frac{S 1}{S 12}$
 1968

Reset the wooden post alongside the iron post.

Land, mountainous.
 Soil, rocky clay with rock outcroppings.
 Timber, fir, hemlock, cedar, alder, maple, chinquapin, yew, dogwood, and madrone; undergrowth, young timber, fern, salal, poison oak, Oregon grape, hazel, vine maple, rhododendron, huckleberry, and mountain willow.

From the cor. of secs. 1 and 12 only, on the E. bdy. of the Tp.
 S. 87* 06' W., bet. secs. 1 and 12.

Ascend 25 ft. along N. slope, through scattering timber and dense undergrowth, across logged area.

2.50 Creek, 1 lk. wide, course N. 70* E.; asc. 140 ft. over SE. slope, changing to E. slope.

11.00 Top of ascent on Burnt Mountain, bears N. and S.; desc. 170 ft. over W. slope.

26.00 Dirt road, 10 lks. wide, bears NW., to W., and SE. on curve.

27.70 Creek, 1 lk. wide, course SW.; asc. 30 ft. over SW. slope.

31.00 Spur ridge, bears NE. and SW.; also same road, bears NE. and SW.; desc. 150 ft. over NW. slope.

39.24 Point for the $\frac{1}{4}$ sec. cor. of secs. 1 and 12, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 26 S R 2 W
 $\frac{1}{4} \frac{S 1}{S 12}$
 1968

*FD. 10/82
 BLM ADMIN. SURVEY
 (SEE GTS FILE)*

from which

A fir, 17 ins. diam., bears N. 72* E., 8 lks. dist., mkd. $\frac{1}{4}$ S1 BT.

A fir, 13 ins. diam., bears S. 13* W., 47 lks. dist., mkd. $\frac{1}{4}$ S12 BT.

The corner is located at the W. edge of logged area.

Descend 785 ft. over steep broken NW. slope, through heavy timber and light undergrowth.

76.25 Creek, 3 lks. wide, course NW.; desc. 60 ft. along N. slope, changing to NW. slope.

78.48 The cor. of secs. 1, 2, 11, and 12.

Land, mountainous.
 Soil, rocky clay with rock outcroppings.