

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 26 S., R. 2 W.

CHAINS

from which the original bearing trees as recorded in the 1959 resurvey

A root hole, bears N. 63 $\frac{1}{2}$ \* E., 53 lks. dist., with an uprooted fir alongside, 30 ins. diam., bark scribed T26S R2W S11 CS BT in 1945.

A sawed fir stump, 36 ins. diam., bears S. 22  $\frac{3}{4}$ \* E., 99 lks. dist., no marks visible.

A sawed fir stump, 30 ins. diam., bears S. 27 $\frac{1}{4}$ \* W., 56 lks. dist., bark scribed S15 CS BT in 1945.

A fir, 36 ins. diam., bears N. 40  $\frac{3}{4}$ \* W., 16 lks. dist., bark scribed T26S R2W S10 CS BT in 1945.

and accessories established in 1959

A mound of stone, 3 ft. base, 2 ft. high, West of the corner.

and bearing trees mkd. by the County Surveyors Office in 1962

A madrone, 8 ins. diam., bears N. 73\* E., 74 lks. dist., with scribe marks S11 CS BT visible on partially healed double blaze.

A maple, 5 ins. diam., bears S. 86\* E., 44 $\frac{1}{2}$  lks. dist., with scribe marks S14 CS BT visible on partially healed double blaze.

A fir, 6 ins. diam., bears N. 79  $\frac{3}{4}$ \* W., 184 $\frac{1}{2}$  lks. dist., with scribe marks S15 CS BT visible on partially healed double blaze.

Land, mountainous.  
Soil, rocky clay with rock outcroppings.  
Timber, fir, cedar, madrone, maple, alder, dogwood, yew, chinquapin, and pine; undergrowth, young timber, fern, salal, vine maple, Oregon grape, hazel, poison oak, ceanothus, manzanita, rhododendron, huckleberry, and mountain willow.

1st MARCH 1971  
a gravel pit near the corner of Sections 10, 11, 14, and 15.  
The average of a number of readings along the lines resurveyed gives a value of 19° 00' East for a mean magnetic declination. There is a range of 3° in local attraction.

COPIES AT REEDSPORT - INDEX GOV'T NOTES, REEDSPORT, TO HERE PAGE 14277

GENERAL DESCRIPTION

The lines resurveyed in township 26 south, range 2 west, are located on the south side of Burnt Mountain between Burnt Creek and Susan Creek about six miles east of Idleyld Park, Oregon. The elevations range from about 1300 feet where the line between Sections 11 and 14 crosses Susan Creek to about 3440 feet above sea level on the East half mile between Sections 1 and 12. The area drains southerly into the North Umpqua River. The soil is a rocky clay with large rock outcroppings. The timber is predominantly fir with a scattering of hemlock, cedar, madrone, alder, maple, chinquapin, dogwood, yew, pine, and oak. Undergrowth consists chiefly of young timber, fern, salalm poison oak, Oregon grape, vine maple, rhododendron, manzanita, ceanothus, hazel, huckleberry, and mountain willow.

The majority of the private land in the area has been logged and most of the remaining commercial timber is located on the public lands. Access into the area is gained by gravelled and dirt roads leading from the North Umpqua River Highway to several abandoned sawmill sites and logging activities. A cattle ranch was noted in sections 12 and 13. Several cabins were noted along Susan Creek in section 11. Numerous deer were noted throughout the area.

No mineral deposits were noted in the area except for (see margin)