

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 26 S. R. 7 W.

CHAINS

from which the remaining original bearing tree

A root hole, bears S. 35° E., 45 lks. dist., with an uprooted and sawed fir stump, 30 ins. diam., with fragmentary scribe marks visible on partially rotted blaze.

and bearing trees mkd. by Byron in 1959

A fir, 17 ins. diam., bears N. 41° E., 42½ lks. dist., with a healed blaze.

A fir, 12 ins. diam., bears S. 60° W., 48½ lks. dist., with a healed blaze.

A fir, 9 ins. diam., bears N. 66½° W., 47 lks. dist., with a healed blaze.

and a new bearing tree

A fir, 10 ins. diam., bears S. 62½° E., 269½ lks. dist., mkd. T26S R7W S10 BT.

Land, mountainous.

Soil, rocky clay with rock outcroppings.

Timber, fir, hemlock, cedar, madrone, alder, maple, yew, oak, and chinquapin: undergrowth, young timber, fern, salal, hazel, arrowwood, huckleberry, salmonberry, and ceanothus.

From the ¼ sec. cor. of secs. 16 and 17, determined at record bearing and distance from the remaining original bearing tree:

A decayed fir snag, 15 ins. diam., bears S. 40° W., 35 lks. dist., with scribe marks ¼ S visible on bark.

At the corner point

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 26 S R 7 W

¼
S 17 | S 16
1967

from which new bearing trees

A fir, 53 ins. diam., bears S. 36° E., 46 lks. dist., mkd. ¼ S16 BT.

A fir, 45 ins. diam., bears S. 72° W., 52 lks. dist., mkd. ¼ S17 BT.

N. 0° 31' W., bet. secs. 16 and 17.

Ascend 150 ft. over SE. slope, through heavy timber and dense undergrowth, along W. edge of logged area.

4.20 Spur, slopes S. 60° E.; desc. 25 ft. over NE. slope.

7.35 Bottom of descent, slopes E.; asc. 235 ft. over SE. slope.