

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 26 S., R. 7 W.

CHAINS

A fir, 10 ins. diam., bears West, 17 lks. dist., mkd.
with a healed blaze.

Ascend 260 ft. over broken NE. slope.

37.70 Creek, 3 lks. wide, course NE.; asc. 55 ft. over NE. slope.

39.90 Point for the $\frac{1}{4}$ sec. cor. of secs. 4 and 9, at proportionate
distance; there is no remaining evidence of the original
corner.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins.
in the ground, with brass cap mkd.

T 26 S R 7 W

$\frac{1}{4}$ $\frac{S 4}{S 9}$

1967

from which

A fir, 18 ins. diam., bears N. 16° E., $77\frac{1}{2}$ lks. dist.,
mkd. $\frac{1}{4}$ S4 BT.

A fir, 40 ins. diam., bears S. 12° E., $77\frac{1}{2}$ lks. dist.,
mkd. $\frac{1}{4}$ S9 BT.

Ascend 2 ft. over NE. slope.

40.75 Spring seepage, 1 lk. wide, course NE.; asc. 600 ft. over
E. slope.

68.10 Dirt road, 20 lks. wide, bears NE. and SW.

70.40 Dirt road, 20 lks. wide, bears N. and S.

79.80 The cor. of secs. 4, 5, 8 and 9.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, madrone, alder, maple, yew,
chinquapin, and oak; undergrowth, young timber, fern, salal,
poison oak, hazel, arrowwood, vine maple, Oregon grape,
blackberry, wild rose, and salmonberry.

From the cor. of secs. 8, 9, 16 and 17.

S. $86^\circ 21'$ W., bet. secs. 8 and 17.

descend 60 ft. over NW. slope, through heavy timber and dense
undergrowth.

9.50 Bottom of descent, slopes N. 35° W.; asc. 20 ft. over NE. slope.

11.50 Spur, slopes NW.; desc. 165 ft. over SW. slope.

19.68 Point for the E $\frac{1}{16}$ sec. cor. of secs. 8 and 17.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in
the ground, with brass cap mkd.

E $\frac{1}{16}$ $\frac{S 8}{S 17}$

1967

from which