

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 29 S., R. 7 W.

CHAINS

A fir, 7 ins. diam., bears N. 67° W., 31½ lks. dist.,
mkd. ± S21 BT.

Ascend 40 ft. over SW. slope.

48.00 Spur, slopes W.; desc. 375 ft. over NW. slope.

69.50 Bottom of descent, slopes W.; asc. 55^{OVER} SW. slope.

73.20 Ridge, bears N. 80° W. and S. 80° E.; desc. 140 ft. over
NE. slope.

79.64 Point for the cor. of secs. 15, 16, 21 and 22, at proportionate
distance; there is no remaining evidence of the original
corner.

From this point, the cor. of secs. 15, 16, 21 and 22, erroneously
reestablished by Thielsen, in 1957, bears South, 0.197 chs. dist.,
set, marked and witnessed as described in official record. I
remove the iron post, and at the corner point

Reset the iron post, 36 ins. long, 2 ins. diam., 28 ins. in
the ground, with brass capmkd.

*FD. BY 5/19/98
H. Johnson
M 87-76*

T 29 S R 7 W
S 16 | S 15
S 21 | S 22
1966
1957

from which bearing trees marked by Thielsen

A fir, 59 ins. diam., bears N. 58° E., 74 lks. dist.,
with healed blaze.

A fir, 33 ins. diam., bears S. 24° W., 49 lks. dist.,
with healed blaze.

and new bearing trees

A fir, 24 ins. diam., bears S. 51° E., 81 lks. dist.,
mkd. T29S R7W S22 BT.

A fir, 7 ins. diam., bears N. 67° W., 11 lks. dist.,
mkd. T29S R7W S16 BT.

I destroy the marks on the 1957 bearing trees to the
SE. and NW.

Land, mountainous.
Soil, rocky clay loam.
Timber, fir, cedar, pine, oak, maple, madrone, alder, and
chinquapin; undergrowth, vine maple, hazel, poison oak,
ocean spray, fern huckleberry, and blackberry.

From the cor. of secs. 14, 15, 22 and 23, monumented with an
iron post, 2 ins. diam., firmly set, extending 8 ins. above
the ground, with brass cap marked and witnessed as described
in the official record.

N. 85° 38' W., bet. secs. 15 and 22.

Descend 30 ft. over SW. slope, through heavy timber and dense
undergrowth.