

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 29 S., R. 7 W.

CHAINS

COUNTY SURVEYORS OFFICE

T 29 S R 7 W

S 20 | S 21

S 29 | S 28

1954

from which the remaining original bearing trees

The rotted remains of an oak stump, size indeterminate, bears N. 21° E., 19 lks. dist.

A rotted oak stump, 15 ins. diam., bears S. 20° E., 81 lks. dist., with scribe marks S BT visible in negative on overgrowth.

A down oak, 24 ins. diam., bears N. 24° W., 80 lks. dist., with rotted blaze, no marks remaining.

and bearing trees marked by Byron, in 1962

A fir, 16 ins. diam., bears N. 56½° E., 133 lks. dist., with scribe marks T29S R7W S21 CS BT visible on partly healed double blaze.

A fir, 13 ins. diam., bears N. 4° W., 86 lks. dist., with healed double blaze.

and a bearing tree of which I have no record

A fir snag, 8 ins. diam., bears S. 50½° W., 22½ lks. dist., with healed double blaze.

and new bearing trees

A fir, 10 ins. diam., bears S. 31½° E., 160 lks. dist., mkd. T29S R7W S28 BT.

A fir, 7 ins. diam., bears S. 50½° W., 140 lks. dist., mkd. T29S R7W S29 BT.

Add HLM 1966 to Brass Cap.

Land, rolling hills.

Soil, rocky clay loam.

Timber, fir, cedar, pine, oak, maple, madrone, alder and chinquapin; undergrowth, vine maple, hazel, poison oak, ocean spray, fern, Oregon grape, huckleberry, and blackberry.

N. 0° 37' E., bet. secs. 20 and 21.

Descend 65 ft. along W. slope, changing to NW. slope, across logged area, through scattering timber and dense undergrowth.

5.60 Dirt road, 10 lks. wide, bears N. 10° E. and S. 10° W.

25.65 Dirt road, 15 lks. wide, bears N. 70° W. and S. 70° E.

34.50 Olalla Creek, 50 lks. wide, course NE.; asc. 15 ft. over SE. slope.

39.00 County road, paved surface, 30 lks. wide, bears N. 20° E. and S. 20° W.

39.82 Point for the ¼ sec. cor. of secs. 20 and 21, at proportionate distance; there is no remaining evidence of the original corner.