

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 29 S., R. 7 W.

## CHAINS

A fir, 13 ins. diam., bears N. 75° W., 22 lks. dist.,  
with healed double blaze.

and bearing trees marked by Byron, in 1957

A down fir, 18 ins. diam., bears S. 38° E., 94 lks.  
dist., with healed double blaze.

A white fir, 12 ins. diam., bears N. 24° W., 62 lks.  
dist., with healed double blaze.

from which new bearing trees

A fir, 10 ins. diam., bears N. 38½° E., 119 lks. dist.,  
mkd. T29S R7W S16 BT.

A fir, 10 ins. diam., bears S. 41½° E., 88 lks. dist.,  
mkd. T29S R7W S21 BT.

A fir, 17 ins. diam., bears S. 88° W., 163 lks. dist.,  
mkd. T29S R7W S20 BT.

Land, rolling hills.

Soil, rocky clay loam.

Timber, fir, cedar, pine, oak, maple, madrone, alder and  
chinquapin; undergrowth, vine maple, hazel, poison oak, ocean  
spray, fern, Oregon grape, huckleberry, and blackberry.

From the cor. of secs. 15, 16, 21 and 22.

N. 89° 09' W., bet. secs. 16 and 21.

Ascend 280 ft. over NE. slope, through heavy timber and  
dense undergrowth.

10.60 Ridge, bears N. 70° W. and S. 70° E.; asc. 130 ft. along  
broken S. slope.

31.00 Top of Dickerson Rocks; bears N. 60° E. and SW.; desc.  
295 ft. over NW. slope; also enger logged area, edge  
bears generally same as Dickerson Rocks.

38.11 Point for the ¼ sec. cor. of secs. 16 and 21, at proportionate  
distance; there is no remaining evidence of the original  
corner.

Set an ironpost, 28 ins. long, 2½ ins. diam., 23 ins.  
in the ground, with brass cap mkd.

T 29 S R 7 W  
¼ S 16  
¼ S 21  
1966

from which

A fir, 30 ins. diam., bears N. 30½° E.; 77 lks.  
dist., mkd. ¼ S16 BT.

A fir, 28 ins. diam., bears S. 84° W., 14 lks.  
dist., mkd. ¼ S21 BT.

Descend 500 ft. over NW. slope, changing to W. slope.

52.60 Ravine, drains N. 65° W.; desc. 60 ft. over W. slope.