

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 21, T. 29 S., R. 7 W.

CHAINS	
70.00	Top of rock bluff, 100 ft. high, bears E. and W.; asc. 10 ft. over SW. slope.
71.50	Top of Dickerson Rocks, bears N. 20° E. and S. 55° W.; desc. 175 ft. over NW. slope.
79.70	The $\frac{1}{4}$ sec. cor. of secs. 16 and 21.
	From the $\frac{1}{4}$ sec. cor. of secs. 21 and 22.
	N. 89° 10' W., on the E. and W. center line of sec. 21.
	Descend 390 ft. over W. slope, changing to broken NW. slope, through heavy timber and dense undergrowth.
19.23	Point for the center E 1/16 sec. cor. of sec. 21.
	Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 23 ins. in the ground, with brass cap mkd.
	$\frac{C \ E \ 1/16 \ C}{S \ 21}$ 1966
	from which
	A fir, 9 ins. diam., bears N. 54° W., 39 lks. dist., mkd. CE 1/16 S21 BT.
	A fir, 20 ins. diam., bears S. 38° E., 32 lks. dist., mkd. CE 1/16 S21 BT.
	Descend 90 ft. over NW. slope.
22.35	Ravine, drains S. 50° W.; asc. 140 ft. over SE. slope.
31.50	Top of ascent, slopes S.; desc. 30 ft. over SW. slope.
38.46	The center $\frac{1}{4}$ sec. cor. of sec. 21.
	Descend 150 ft. over SW. slope, changing to W. slope.
42.50	Leave timber; enter logged area, edge bears N. and S.
52.00	Spur, slopes S. 70° W.; desc. 60 ft. over NW. slope.
57.91	Point for the center W 1/16 sec. cor. of sec. 21.
	Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
	$\frac{C \ W \ 1/16 \ C}{S \ 21}$ 1966
	from which
	A fir, 8 ins. diam., bears N. 13° E., 17 $\frac{1}{2}$ lks. dist., mkd. CW 1/16 S21 BT.
	A oak, 18 ins. diam., bears S. 11° E., 41 $\frac{1}{2}$ lks. dist., mkd. CW 1/16 S21 BT.
74.60	Olalla Creek, 30 lks. wide, course N.; asc. 20 ft. over E. slope.
77.04	County road, paved surface, 30 lks. wide, bears N. 20° E. and S. 20° W.
77.36.	The $\frac{1}{4}$ sec. cor. of secs. 20 and 21