

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 23 S., R. 1 W.

CHAINS

A cedar, 10 ins. diam., bears N. $25\frac{3}{4}^{\circ}$ W., 35 lks. dist.,
mkd. $\frac{1}{16}$ S3 BT.

Ascend 290 ft. over SE. slope.

28.75 Spur, slopes E.; desc. 35 ft. over NE. slope.

31.30 Bottom of descent, slopes E.; asc. 35 ft. over SE. slope.

40.18 Point for the $\frac{1}{4}$ sec. cor. of secs. 2 and 3, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 23 S R 1 W
 $\frac{1}{4}$
 S 3 | S 2
 1964

from which

A cedar, 8 ins. diam., bears N. $82\frac{1}{2}^{\circ}$ E., 18 lks. dist.,
mkd. $\frac{1}{4}$ S2BT.

A cedar, 9 ins. diam., bears West, 18 lks. dist., mkd.
 $\frac{1}{4}$ S3 BT.

Ascend 45 ft. over SE. slope.

43.75 Spur, slopes N. 70° E.; desc. 760 ft. over NE. slope.

77.10 Dirt road, 15 lks. wide, bears N. 50° W. and S. 70° E.

81.57 The cor. of secs. 2, 3, 34, and 35, on the N. bdy. of the Tp.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, hemlock, alder, maple, chinquapin, yew, dogwood cascara, madrone, pine, and oak; undergrowth, vine maple, hazel, arrowwood, rhododendron, huckleberry, blackberry, wild rose, salal, Oregon grape, poison oak, sword fern and bracken.

From the cor. of secs. 10, 11, 14, and 15.

S. $89^{\circ} 38'$ W., bet. secs. 10 and 15.

Ascend 130 ft. over precipitous NE. slope, through heavy timber and moderate undergrowth.

2.55 Spur, slopes N.; desc. 35 ft. over NW. slope.

3.70 Top of rock bluff, 135 ft. high, bears NE. and SW.; desc. over bluff.

5.10 Bottom of same bluff, bears NE. and SW.; desc. 190 ft. over NW. slope.

10.35 Ravine, drains N. 10° W.; asc. 235 ft. over broken and precipitous NE. slope.

20.70 Spur, slopes N. 10° W.; desc. 75 ft. over NW. slope.

22.55 Top of rock bluff, 35 ft. high, bears, NE. and SW.; desc. over bluff