

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 23 S., R. 1 W.

CHAINS

74.50 Spur, slopes N. 60° E.; desc. 205 ft. over NW. slope.

79.85 Creek, 4 lks. wide, course N. 70° E.; asc. 30 ft. over SE. slope.

80.48 Point for the cor. of secs. 3, 4, 9, and 10, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2½ ins. diam., 14 ins. in the ground to bedrock, and in a mound of stone, 3 ft. base, to top, with brass cap mkd.

T 23 S R 1 W
 S 4 | S 3
 , S 9 | S 10
 1966

from which

- A hemlock, 16 ins. diam., bears N. 40° E., 25 lks dist. mkd. T23S R1W S3 BT.
- A hemlock 6 ins. diam., bears S. 42 3/4° E., 22 lks. dist. mkd. T23S R1W S10 BT.
- A hemlock, 11 ins. diam., bears S. 32½° W., 44½ lks. dist., mkd. T23S R1W S9 BT.
- A hemlock, 13 ins. diam., bears N. 4½° W., 65 lks. dist. mkd. T23S R1W S4 BT.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, maple, alder, yew, cascara, madrone, chinquapin, pine, and oak; undergrowth, hazel, arrowwood, vine maple, rhododendron, salal, Oregon grape, wild rose, huckleberry, blackberry, sword fern and bracken.

From the cor. of secs. 2, 3, 10, and 11.

S. 89° 32' W., bet. secs. 3 and 10.

Ascend 85 ft. over SE. slope, through heavy timber and light undergrowth.

2.65 Spur, slopes S. 30° E.; desc. 365 ft. over SW. slope.

19.925 Point for the E 1/16 sec. cor. of secs. 3 and 10.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

E 1/16 S 3
 S 10
 1964

from which

- A cedar, 18 ins. diam., bears N. 47° W., 17½ lks. dist., mkd. E1/16 S3 BT.
- A fir, 18 ins. diam., bears S. 35° E., 49 lks. dist., mkd. E1/16 S10 BT.

Descend 60 ft. over SW. slope.