

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 23 S. R. 1 W.

CHAINS

- 26.15 Creek, 3 lks. wide, course S. 35° W.; asc. 5 ft. over SE. slope.
- 27.55 Top of ascent, slopes S.; desc. 20 ft. over SW. slope.
- 28.70 Creek, 12 lks. wide, course S. 60° E.; asc. 25 ft. over NE. slope.
- 34.10 Same creek, 12 lks wide, course N. 75° E.; asc. 115 ft. over SE. slope
- 39.85 Point for the  $\frac{1}{4}$  sec. cor. of secs. 3 and 10, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T 23 S R 1 W  
 $\frac{1}{4}$   $\frac{S 3}{S 10}$   
 1966

from which

A fir, 45 ins. diam., bears N. 5° W.,  $9\frac{1}{2}$  lks. dist., mkd.  $\frac{1}{4}$  S3 BT.

A fir, 10 ins. diam, bears S.  $33\frac{1}{2}$ ° E.,  $23\frac{1}{2}$  lks. dist. mkd.  $\frac{1}{4}$  S10 BT.

Ascend 80 ft. over SE. slope.

- 47.50 Spur, slopes S.; asc. 90 ft. over SE. slope.

- 59.775 Point for the W  $\frac{1}{16}$  sec. cor. of secs. 3 and 10.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd.

W  $\frac{1}{16}$   $\frac{S 3}{S 10}$   
 1966

from which

A cedar, 25 ins. diam., bears N. 12° E., 34 lks. dist. mkd. W $\frac{1}{16}$  S3 BT.

A hemlock, 50 ins. diam., bears S.  $74\frac{1}{2}$ ° W.,  $35\frac{1}{2}$  lks. dist., mkd. W $\frac{1}{16}$  S10 BT.

Ascend 385 ft. over broken SE. slope.

- 79.70 The cor. of secs. 3, 4, 9, and 10.

Land, mountainous.  
 Soil, rocky clay.  
 Timber, fir, hemlock, cedar, maple, alder, cascara, yew, dogwood, chinquapin, madrone, pine, and oak; undergrowth, vine maple, rhododendron, hazel, arrowwood, huckleberry, blackberry, salmonberry, poison oak, wild rose, salal, Oregon grape, sword fern and bracken.

N. 0° 09' W., bet. secs. 3 and 4.

Ascend 65 ft. over SE. slope, through heavy timber and light undergrowth.