

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines. T. 23 S., R. 1 W.

## CHAINS

- 2.80 Spur, slopes S.  $75^{\circ}$  E.; desc. 10 ft. over NE. slope.
- 3.10 Creek, 3 lks. wide, course S.  $80^{\circ}$  E.; asc. 140 ft. over SE. slope.
- 9.65 Top of ascent, slopes E.; desc. 35 ft. over NE. slope.
- 12.90 Ravine, drains S.  $80^{\circ}$  E.; asc. 225 ft. over SE. slope.
- 15.60 Dirt road, 15 lks wide, bears E. and SW.
- 20.085 Point for the S  $1/16$  sec. cor. of secs. 3 and 4.
- Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.
- S  $1/16$   
S 4|S 3  
1966
- from which
- A hemlock, 6 ins. diam., bears N.  $51\frac{1}{2}^{\circ}$  E., 26 lks. dist., mkd. S $1/16$  S3 BT.
- A hemlock, 6 ins. diam., bears S.  $5^{\circ}$  W., 9 lks. dist., mkd. S $1/16$  S4 BT.
- Ascend 60 ft. over SE. slope.
- 25.50 Ridge, dividing Buck Creek and Walker Creek drainages, bears E. and W.; desc. 465 ft. over NE. slope.
- 40.17 Point for the  $\frac{1}{4}$  sec. cor. of secs. 3 and 4, at proportionate distance; there is no remaining evidence of the original corner.
- Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.
- T 23 S R 1 W  
 $\frac{1}{4}$   
S 4|S 3  
1966
- from which
- A hemlock, 27 ins. diam., bears S.  $30\frac{1}{2}^{\circ}$  E., 57 lks. dist., mkd.  $\frac{1}{4}$  S3 BT.
- A cedar, 8 ins. diam., bears West.  $26\frac{1}{2}$  lks. dist., mkd.  $\frac{1}{4}$  S4 BT.
- Descend 510 ft. over NE. slope.
- 60.255 Point for the N  $1/16$  Sec. cor. of secs. 3 and 4.
- Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.
- N  $1/16$   
S 4|S 3  
1966
- from which
- A cedar, 23 ins. diam., bears N.  $33^{\circ}$  E.,  $26\frac{1}{2}$  lks. dist., mkd. N $1/16$  S3 BT.