

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 23 S., R. 1 W

CHAINS

A root hole bears S. 61° E., 86 lks. dist., with a down hemlock alongside, 34 ins. diam., with scribe marks T23S R1W S16 CS BT visible on open blaze.

A fir, 63 ins. diam., bears S. 73½° W., 57 lks. dist., with scribe marks T23S R1W S17 CS BT visible on open blaze.

A sawed fir stump, 45 ins. diam., bears N. 11¼° W., 76 lks. dist., with fragmentary scribe marks visible on partially healed blaze. (Record, N. 14° W.)

The corner point is located in Lilly Creek, 12 lks. wide, course N. 75° W., where it is impracticable to establish a permanent monument.

Land, mountainous.

Soil, rocky clay.


Timber, fir, hemlock, cedar, alder, maple, chinquapin, yew, dogwood, cascara, madrone, pine, and oak; undergrowth, vine maple, hazel, arrowwood, rhododendron, huckleberry, blackberry, salal, Oregon grape, wild rose, skunk cabbage, poison oak, sword and bracken fern.

N. 2° 25' W., bet. secs. 8 and 9.

Ascend 10 ft. over SW. slope, through heavy timber and moderate undergrowth.

0.38 Point selected for the witness cor. to the cor. of secs. 8, 9, 16, and 17.

Set an iron post, 28 ins. long, 2½ ins. diam., 25 ins. in the ground with brass cap mkd.



from which

A hemlock, 20 ins. diam., bears N. 89° E., 40½ lks. dist., mkd. X BT.

A hemlock, 25 ins. diam., bears S. 14½° E., 114 lks. dist., mkd. X BT.

A hemlock, 18 ins. diam., bears S. 50° W., 75½ lks. dist., mkd. X BT.

A yew, 13 ins. diam., bears N. 11½° W., 91 lks. dist., mkd. X BT.

Ascend 565 ft. over SW. slope.

24.35 Spur, slopes S. 70° W.; desc. 90 ft. over NW. slope.

28.10 Creek, 3 lks. wide, course W.; asc. 430 ft. over SW. slope.