

## County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 23 S., R. 1 W.

## CHAINS

A yew, 6 ins. diam., bears N.  $8\frac{1}{2}^{\circ}$  E., 56 lks. dist., mkd. T23S RLW S4 BT.

A yew, 10 ins. diam., bears S.  $38\frac{1}{2}^{\circ}$  E., 64 lks. dist., mkd. T23S RLW S9 BT.

A hemlock, 13 ins. diam., bears N.  $1^{\circ}$  W.,  $54\frac{1}{2}$  lks. dist., mkd. T23S RLW S5BT.

Reset the iron pipe alongside the iron post.

Land, mountainous.

Soil, rocky clay,

Timber, fir, hemlock, cedar, yew, maple, alder, cascara, dogwood, chinquapin, madrone, pine, and oak; undergrowth, vine maple, hazel, arrowwood, rhododendron, huckleberry, blackberry, wild rose, salal, Oregon grape, poison oak, sword fern and bracken.

From the cor. of secs. 3, 4, 9, and 10.

S.  $89^{\circ} 51'$  W., bet. secs. 4 and 9.

Ascend 765 ft. over SE. slope, through heavy timber and moderate undergrowth/

34.15 Dirt road, 15 lks. wide, bears N.  $30^{\circ}$  E. and S.  $20^{\circ}$  W.

39.15 Dirt road, 15 lks. wide, bears N.  $30^{\circ}$  W. and S.  $30^{\circ}$  E.

39.51 Point for the  $\frac{1}{4}$  sec. cor. of secs. 4 and 9, at proportionate distance: there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T 23 S R 1 W  
 $\frac{1}{4}$  S 4  
 $\frac{1}{4}$  S 9  
 1966

from which

A fir, 50 ins. diam., bears N.  $62^{\circ}$  E., 52 lks. dist., mkd.  $\frac{1}{4}$  S4 BT.

A yew, 12 ins. diam., bears S.  $13^{\circ}$  W.,  $33\frac{1}{2}$  lks. dist. mkd.  $\frac{1}{4}$  S9 BT.

Ascend 10 ft. over SE. slope.

40.25 Ridge, dividing Sharps Creek and Mosby Creek drainages bears N and S.; desc. 685 ft. over NW. slope.

61.00 Dirt road, 15 lks. wide, bears N.  $10^{\circ}$  E. and S.  $10^{\circ}$  W.

73.75 Creek, 4 lks. wide, course S.  $10^{\circ}$  W.; asc 60 ft. over general SE. slope.

79.02 The cor. of secs. 4, 5, 8, and 9.