

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines. T. 23 S., R. 1 W.

CHAINS

A fir, 58 ins. diam., bears S. $6\frac{1}{2}^{\circ}$ W., $63\frac{1}{2}$ lks. dist.,
mkd. N1/16 S5 BT.

Reset the ironpipe alongside the iron post.

The corner is located at SE. cor. of logged area, edges bear
N. and W.

N. $0^{\circ} 22'$ E.; beginning new measurement.

Descend 90 ft. over broken NE. slope.

14.60 Gravelled road, 25 lks. wide, bears N. 70° E. and S. 70° W.

17.95 Same road, 25 lks. wide, bears. NW. and SE.

21.71 The cor. of secs. 4, 5, 32, and 33, on the N. bdy. of the Tp.

Land, mountainous

Soil, rocky clay.

Timber, fir, hemlock, yew, cedar, maple, alder, cascara, dogwood,
chinquapin, madrone, pine, and oak; undergrowth, vine maple,
hazel, arrowwood, rhododendron, huckleberry, blackberry, salal,
Oregon grape, wild rose, sword fern and bracken.

From the cor. of secs. 29, 30, 31, and 32, monumented with the
original sandstone, now broken and loosely set, marked with
5 notches on the E. and 1 notch on the S. face, from which
the original bearing trees:

A hemlock, 32 ins. diam., bears N. 76° E., 67 lks. dist.
with fragmentary scribe marks visible on partially
healed blaze.

A fir, 43 ins. diam. bears S. $22\frac{1}{2}^{\circ}$ E., 19 lks. dist.,
with healed blaze.

A fir, 33 ins. diam., bears S. $82\frac{1}{2}^{\circ}$ W., 15 lks. dist., with
fragmentary scribe marks visible on opened blaze.

A fir, 58 ins. diam., bears N. 16° W., 57 lks. dist.,
with healed blaze.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 16 ins. in the
ground, to bedrock, and in a mound of stone, 3 ft. base, to
top, with brass cap mkd.

T 23 S R 1 W
S 30 | S 29
S 31 | S 32
1964

Deposit the corner stone alongside the iron post.

N. $89^{\circ} 58'$ W., bet. secs. 30 and 31.

Descend 975 ft. over W. slope, through heavy timber and moderate
undergrowth.

30.69 Middle Fork Mosby Creek, 20 lks. wide, couse N. 30° W.; asc.
269 ft. over NE. slope.