

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, T. 23 S., R. 1 W.

CHAINS

A hemlock, 10 ins. diam., bears N. $34\frac{1}{2}^\circ$ W., 14 lks. dist., mkd. 80 1/16 S6 BT.

A hemlock, 13 ins. diam., bears S. $5\frac{1}{2}^\circ$ E., 36 lks. dist., mkd. 80 1/16 S7 BT.

Ascend 65 ft. over NE. slope.

41.85 Spur, slopes N. 20° E.; asc. 20 ft. over NE. slope.

49.05 Spur, slopes N. 10° W.; desc. 605 ft. over general W. slope.

70.65 Ravine, drains N. 30° W.; asc. 5 ft. over NE. slope.

74.85 Spur, slopes N. 55° W.; desc. 70 ft. over W. slope.

75.15 Enter Mosby Creek bottom, edge bears generally N. and S.; desc. 5 ft. over W. slope.

78.95 Gravelled road, 30 lks. wide, bears N. 20° W. and S. 20° E.

79.25 Point for the 120 1/16 sec. cor. of secs. 6 and 7, falls on W. edge of gravelled road.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., the top 10 ins. below the surface of the road with brass cap mkd.

1/16 $\frac{S\ 6}{S\ 7}$ 120
1966

from which

A sawed fir stump, 36 ins. diam., bears N. 84° W., 68 lks. dist., mkd. 120 1/16 S6 BT.

A fir, 21 ins. diam., bears S. $74\ 3/4^\circ$ E., $96\frac{1}{2}$ lks. dist., mkd. 120 1/16 S7 BT.

Descend 25 ft. across bottom land.

85.85 Mosby Creek, 30 lks. wide, course N. 25° W.; asc. 25 ft. over NE slope.

87.00 Leave bottom land, edge bears generally N. and S.; asc. 205 ft. over E. slope.

91.73 The cor. of secs. 1, 6, 7, and 12, on the W. dby. of the Tp., monumented with an iron post, $2\frac{1}{2}$ ins. diam., firmly set, protruding 3 ins. above ground, with brass cap marked and witnessed as described in the record of the 1960 dependent resurvey.

Land, Mountainous.

Soil, rocky clay.

Timber, fir, cedar, hemlock, yew, maple, alder, cascara, madrone, chinquapin, pine, and oak; undergrowth, salal, hazel, arrowwood, vine maple, rhododendron, wild rose, Oregon grape, huckleberry, blackberry, elderberry, sword fern and bracken.